

CORPORATION OF THE TOWNSHIP OF MCKELLAR

December 5, 2023 – 6:30 p.m.

AGENDA

Topic: Regular Council Meeting

Time: December 5, 2023 6:30 P.M.

Closed Session Beginning at 5:30 P.M.

Join Zoom Meeting

<https://us06web.zoom.us/j/88919024555>

Dial by your location

+1 647 374 4685 Canada

+1 647 558 0588 Canada

23-746 1st resolution

2023-78 1st by-law

- 1. CALL TO ORDER**
- 2. ROLL CALL**
- 3. DECLARATIONS OF PECUNIARY AND/OR PERSONAL INTEREST AND GENERAL NATURE THEREOF**
- 4. ADOPTION OF AGENDA**
- 5. CLOSED SESSION**
 - 5.1 Minutes of Closed Session – November 21, 2023 & November 24, 2023
 - 5.2 Personal matters about an identifiable individual, including Municipal or local board employees, pursuant to Ontario Municipal Act, Section 239(2)(b) – Staffing
 - 5.3 Litigation or Potential Litigation, pursuant to Section 239(2)(e) – Litigation re. Consent Application Appeal, Ontario Land Tribunal
 - 5.4 Acquisition or Disposition of Land; pursuant to Ontario Municipal Act, Section 239(2)(c) – Land Acquisition
- 6. CALL TO ORDER – REGULAR SESSION 6:30pm (Public can join via Zoom)**
- 7. RESPECT AND ACKNOWLEDGMENT DECLARATION**

In the spirit of reconciliation and co-operation, we wish to acknowledge that the land on which we gather is the traditional territory of the Anishinaabe and Mississauga people. Its boundaries fall within the Robinson-Huron Treaty of 1850 and the Williams Treaty of 1923. We are grateful to live here and we thank all the generations of people who have taken care of this land for thousands of years. To honour the suffering of Indigenous people and the love and wisdom they have carried for thousands of years, we pledge to work in community and

harmony with each other and the environment we inhabit and work towards Truth and Reconciliation.

8. ROLL CALL

9. DECLARATIONS OF PECUNIARY AND/OR PERSONAL INTEREST AND GENERAL NATURE THEREOF

10. PUBLIC MEETING

11. DELEGATIONS AND PRESENTATIONS

11.1 GHD, 2023 Municipal Structure Inventory and Inspection Report

11.2 FoodCycler Science, Municipal Food Waste Diversion Program

12. COMMITTEE OF THE WHOLE

13. MOTION TO REVIEW A PREVIOUS MOTION

14. ADOPTION OF MINUTES OF PREVIOUS MEETING(S)

14.1 November 21, 2023 Regular Meeting of Council and November 24, 2023 Special Meeting of Council Minutes

15. PLANNING MATTERS

15.1 Conditions Met Letter Consent Application No. B02/2023 (Dyment)

16. COMMITTEE/BOARD MINUTES WITH RECOMMENDATIONS FOR APPROVAL

16.1 Board of Health Minutes – September 27, 2023

17. STAFF REPORTS WITH RECOMMENDATIONS FOR APPROVAL

17.1 KPMG Forensic Audit

18. MAYOR'S REPORT

19. CORRESPONDENCE FOR CONSIDERATION

19.1 National Housing Accord's Call to End Canada's Rental Housing Crisis

19.2 Town of Parry Sound Resolution to Request Education Minister to Not Close Rural Schools

19.3 Declare January 2024 as Crime Stoppers Month

20. MOTION AND NOTICE OF MOTION

20.1 Annual Christmas Bonus for Municipal Employees

20.2 St. Stephen's Church Renovations Tender

20.3 Christmas Holiday Hours – Municipal Office and Transfer Station

21. BY-LAWS

- 21.1 By-law 2023-73 Being a By-law to Impose Charges on Property Owners in a Designated Area (Craigmore Subdivision) for the Provision of Road Upgrades by The Township – Third Reading
- 21.2 By-law 2023-66 Being a By-law to Regulate the Speed of Motor Vehicles on Certain Highways within the Municipality – Third Reading

22. UNFINISHED BUSINESS

- 22.1 Unfinished Business as of December 5, 2023

23. NEW BUSINESS

24. PUBLIC NOTICES, ANNOUNCEMENTS, INQUIRIES AND REPORTS BY COUNCIL MEMBERS

25. CONSENT AGENDA – CORRESPONDENCE

- 25.1 AMO Watchfiles (November 16, 2023 & November 23, 2023)
- 25.2 Municipality of Shuniah, Unnecessary Noise from Engine Brakes
- 25.3 Prince Edward County, Guaranteed Livable Wage Income
- 25.4 Prince Edward County, Stop MECP Proposal to Expand the Use of the Permit-by-Rule to Waste Management Systems, Storm Water & Water Taking Activities
- 25.5 Town of Orangeville, Ontario Works Financial Assistance Rates
- 25.6 Municipality of South Bruce, Limitations on Hauled Sewage Disposal Sites
- 25.7 West Parry Sound Economic Development Collaborative Support
 - (i) Township of the Archipelago
 - (ii) Town of Parry Sound
 - (iii) Township of Carling
- 25.8 Township of McKellar's Request to be Released from the West Parry Sound Recreation & Cultural Centre Agreement
 - (i) Township of the Archipelago
 - (ii) Town of Parry Sound
 - (iii) Township of Carling
- 25.9 Municipality of Whitestone, West Parry Sound Recreation & Cultural Centre
- 25.10 Municipal Finance Officer's Association of Ontario, Federal Fall Economic Update 2023
- 25.11 Township of Carling, Design Plans for the West Parry Sound Recreation & Cultural Centre
- 25.12 Town of Goderich, Declaring Intimate Partner Violence an Epidemic
- 25.13 Township of Coleman, Conservation Officer Reclassification

26. QUESTION/COMMENT PERIOD (RELATED TO ITEMS ON AGENDA)

27. CONFIRMING BY-LAW

- 27.1 By-law 2023-78 - Confirming the Proceedings of Council

28. ADJOURNMENT

Instructions for Joining the Council Meeting

1. Please try to sign in between 6:20 to 6:30 if possible; you are still welcome to sign in after 6:30 if necessary.
2. Please wait to be let in the 'meeting room'; this won't take long.
3. Please have your mic and video on mute unless you are speaking; this ensures there are no distractions or background noise to disrupt the meeting.
4. When you sign in, please sign in with your full name (first and last), not a company name.
5. A question-and-answer opportunity will be available at the end of the meeting, as per normal protocol, or during the Public Meeting.
6. If you have permission to speak please identify yourself (first and last name).
7. Please respect meeting protocol and do not interrupt the meeting. The Municipality reserves the right to remove attendees who are disruptive or disrespect meeting protocol.



SCHEDULE "E"

**Township of McKellar
Request for Delegation/Deputation before Council**

Pursuant to By-law No. 2023-08, any person wishing to make a deputation before Council shall submit a request in writing to the Clerk no later than 1:00 p.m. on the Tuesday prior to the meeting the following week at which they wish to be heard. The written request shall be a detailed written submission that clearly outlines the matter that the deputation wishes to present to Council including the nature of the business to be discussed and the person(s) named to make the deputation. The detailed written submission, together with this form, shall be circulated with the Council Agenda. Please note that Deputations are limited to ten (10) minutes in length.

PLEASE PRINT

Name of Person to Appear: Dennis Baxter	
Address: 300 Water Street, Whitby, Ontario	
Phone: _____ Home _____ Cell 289-356-2881 Business 905-429-5010	
Name of person requesting appearance: (if different from the person preparing the request)	
Phone: _____ Home _____ Cell _____ Business 905-429-5010	
Name of Group or Person(s) being represented (if applicable) GHD Limited	
Meeting Date requested to appear before Council 12/5/23	
Subject Matter of Deputation: Municipal Structure Inventory and Inspection _____ _____	
Detailed written submission must be attached or submitted to the Clerk (by 1:00 p.m. the Tuesday of the week prior to the Council Meeting). _____ _____	
Signature: Dennis L Baxter	Date: 11/29/23

Digitally signed by Dennis L. Baxter
Date: 2023.11.29 10:04:18 -0500



SCHEDULE "E" continued

Reminder: A signed detailed written submission must be provided to the Clerk's Office by 1:00 p.m. on the Tuesday of the week prior to the meeting the following week. Failure to provide a signed detailed written submission by the Tuesday of the week prior to the Council Meeting will result in the deputation not being placed on Council's Agenda.

Decorum dictates respect for all opinions and individuals are reminded there is zero tolerance for coarse language and inappropriate behaviour. By submitting this Form, you have indicated agreement with this requirement.

Signage shall be posted in the Council Chambers advising deputations, presenters and the Public that the Meeting proceedings are being audio recorded and will be made available on the municipal website. The Township assumes no liability for the recorded comments of the public that may be construed as false, defamatory or slanderous in nature.

Personal Information on this form is collected under the legal authority of the Municipal Act, S.O. 2001, c25, as amended. The information is collected and maintained for the purpose of creating a record that is available to the general public pursuant to Section 27 of the Municipal Freedom of Information and Protection of Privacy Act. [Municipal Freedom of Information and Protection of Privacy Act, R.S.O. 1990, c. M.56 \(ontario.ca\)](#)

Correspondence to Council:

Be advised that Council and Committee meeting agendas, Minutes and correspondence are public documents and are published on the Township of McKellar website. When corresponding with the Township of McKellar, please be aware that personal correspondence or delegation materials (together with names, addresses, email addresses and phone numbers) may be included on the Council or Committee or Committee of Council meeting agenda and subsequently appear on the corporate website.

If you feel there is a compelling reason that your correspondence to Council should not be included on the agenda and released to the public, please notify the Clerk's office.



Municipal Structure Inventory and Inspection 2023



Township of McKellar

November 20, 2023

➔ **The Power of Commitment**





Project name		Bridge and Culvert Inspections 2023					
Document title		Municipal Structure Inventory and Inspection 2023					
Project number		12604686					
File name		Township of McKellar Report.docx					
Status Code	Revision	Author	Reviewer		Approved for issue		
			Name	Signature	Name	Signature	Date
S4	0	Jeff Parkinson	Dennis Baxter		Benjamin Loucks		11/21/23

GHD Limited

Contact: Dennis Baxter, P.Eng., Senior Manager Bridges |
 65 Sunray Street,
 Whitby, Ontario L1N 8Y3, Canada
 T 289 356 2881 | ghd.com

© GHD 2023

This document is and shall remain the property of GHD. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorized use of this document in any form whatsoever is prohibited.

Executive Summary

The Township of McKellar 2023 Municipal Structure Inventory and Inspection Study provides a summary of structure condition ratings identified during rating surveys conducted by GHD in 2023. All of the Township's structures of 3.0 m span or greater were reviewed in 2023. The Township of McKellar's total inventory of nine (9) structures have been included in this report.

Data collection and structure ratings were completed in accordance with the Municipal Bridge Appraisal and Municipal Culvert Appraisal Manuals and the Ontario Structure Inspection Manual. The scope of the report includes summaries of collected data, with discussion and analysis regarding the same.

A total of seven (7) bridges and two (2) culverts were inspected in 2023. Key items contained within the inspection report are summarized below:

Key items contained within the inspection report are summarized below:

- One (1) bridge has been designated for further engineering investigation to confirm visual repair recommendations at a total cost of **\$15,000**.
- Six (6) bridges require rehabilitation at an estimated cost of **\$1,116,000**.
- One (1) bridge requires guide rail installation, extension or upgrades at a total cost of **\$95,000**. All Now need guide rail requirement costs provided do not include the potential traffic control costs that may be incurred if the guide rail work is undertaken independent of other necessary works.
- A summary of the total structure construction and rehabilitation needs resultant from the 2023 structure inspection for the ten year period is estimated to be **\$1,131,000** for the existing Township's structure system. Of this total cost **\$170,000** are Now needs, **\$810,000** are for structure 1-5 year needs, and **\$151,000** are for 6-10 year needs.

For new structures, the design lifespan is now 75 years; however, structures constructed prior to 2000 were generally designed for a 50 year lifespan. Accordingly, between 1.5% and 2.0% of the value of the entire structure inventory of **\$14,157,000** should be budgeted annually to ensure that the structure inventory can be maintained in perpetuity. It is noted that as the structures are replaced, the annual allocation could be reduced to 1.5%.

Based on the aforementioned structure inventory replacement value of **\$14,157,000** and the data included in this report, for the Township's system the estimated minimum annual capital program for structures should be in the amount of **\$269,000** (1.9%) per year for the Township of McKellar to maintain the current system adequacy. However, given the average age of the Township's structures inventory, it is quite probable that expenditures on structures will be even higher than estimated over the next decade as the older structures reach a terminal condition.

Rehabilitation and replacement recommendations are provided within this report. The costs associated with these recommendations should be budgeted above and beyond the recommended annual capital program. For the ten-year period, the "Not Adjusted for Owners Share" rehabilitation and replacement needs are estimated to be **\$1,131,000** for the existing Township's structure system. The annual value of **\$113,100** associated with these recommendations should be budgeted above and beyond the recommended annual capital program amount of **\$269,000** as shown above to maximize the service life of the structures. The total forecasted expenditures over ten years are currently valued at **\$382,100** annually.

All costs contained within the structure appraisal reports include engineering (15%) and contingencies (20%) and are based on 2023 construction dollars.

Completion of the 2023 re-inspection of seven (7) bridges and two (2) culverts on the Township's road system has resulted in reliable and current data being available to the Township to implement a maintenance program ensuring the Township's structures are kept safe and in good repair. Maintenance of the Bridge and Culvert Management Program will require updating of databases on an on-going annual basis to reflect previous year

rehabilitation/replacement project updates. It is recommended that the structures be re-inspected under the direction of a qualified structural engineer every two (2) years.

This report is subject to, and must be read in conjunction with, the limitations set out in section 1 and the assumptions and qualifications contained throughout the Report.

Contents

1.	Introduction	1
1.1	Purpose of this report	1
2.	Scope and limitations	2
3.	State of the Infrastructure	2
3.1	Structure Categorization	2
3.2	Asset Inventory	3
3.3	Structure Inventory Replacement Value	3
3.4	Asset Age and Condition	3
3.4.1	Asset Age	3
4.	Structure Inventory and Identification of Maintenance, Repair and Replacement Needs	4
4.1	Loading or Dimensional Restrictions	4
4.1.1	Current Service Performance	4
4.1.1.1	Load Limit Bylaws	4
4.2	Engineering Investigations	5
4.3	Structure Removal	5
4.4	Structure Replacements	5
4.5	Structure Rehabilitations	5
4.5.1	Summary of Now Guide Rail Requirements	9
4.6	Monitoring	11
5.	Structure Inventory and Construction Needs Summary	11
6.	Normal Structure Maintenance	12
7.	Recommended Program Funding Levels	13
7.1	Capital Replacements	13
7.2	Major Maintenance	13
8.	Conclusion	14

Table index

Table 1	Asset Inventory	3
Table 2	Structure Replacement Value	3
Table 3	Load Limit Recommendations	4
Table 4	Engineering Investigations	5
Table 5	Bridge Removal	6
Table 6	Culvert Removal	6
Table 7	Bridge Replacements	7
Table 8	Culvert Replacements	7

Table 9	Structure Rehabilitations - Bridges	8
Table 10	Structure Rehabilitations - Culverts	8
Table 11	NOW Guide Rail Requirements - Bridges	9
Table 12	NOW Guide Rail Requirements - Culverts	9
Table 13	Overall Bridge Inventory	10
Table 14	Overall Culvert Inventory	10
Table 15	Monitoring	11
Table 16	Bridge Improvement Needs Summary	11
Table 17	Culvert Improvement Needs Summary	12
Table 18	Normal Structure Maintenance Summary - Bridges	12
Table 19	Normal Structure Maintenance Summary - Culverts	13
Table 20	Material Condition and Performance Condition Ratings (MCR & PCR)	27
Table 21	Functional Needs Ratings for Bridges	27
Table 22	Functional Needs Ratings for Culverts	28
Table 23	Overall Component Condition Rating Weights	28
Table 24	Load Posting Ratings	28

Figure index

Figure 1	Asset Life Consumed Profile	3
----------	-----------------------------	---

Appendices

Appendix A	Key Plan
Appendix B	Bridge Improvement Needs
Appendix C	Culvert Improvement Needs
Appendix D	Bridge and Culvert Management Program
Appendix E	Structure Appraisal Reports

Attachments

No table of contents entries found.

1. Introduction

1.1 Purpose of this report

The Township of McKellar 2023 Municipal Structure Inventory and Inspection Study provides a summary of structure condition ratings identified during rating surveys conducted by GHD in 2023. The Township of McKellar's total inventory of nine (9) structures are included in this report.

The Province of Ontario passed amendments in 1997 to existing legislation in the Highway Traffic Act (HTA), The Bridge Act (BA) and the Public Transportation and Highway Improvement Act (PTHIA) that required all bridge and culvert structures with a span greater than 3.0 m to be inspected under the direction of a Professional Engineer at no greater than two (2) year intervals. The inspection methodology and reporting must be in accordance with the Ontario Structure Inspection Manual (or equivalent).

Under this regulation municipalities are responsible for ensuring that their bridges are kept safe and in good repair. This should be done through the performance of regular bridge inspections in accordance with the Ontario Structure Inspection Manual, or equivalent. A detailed inspection involves a thorough examination of bridge components, along with an assessment of the overall bridge condition.

This study is intended to provide documentation of the existing condition of the Township's structure inventory and establishment of recommendations and cost estimates for repair and/or upgrading of the structures to provide an economical and cost-effective means of maintaining the current infrastructure.

Data collection and structure ratings were completed in accordance with the Municipal Bridge Appraisal and Municipal Culvert Appraisal Manuals and the Ontario Structure Inspection Manual Revised (May 2018). This study is in accordance with the Municipality's legislative requirements of The Public Transportation and Highway Act – Regulation 104/97.

The scope of the report includes summaries of collected data, with discussion and analysis regarding the same.

Also under the new regulations, municipalities are still responsible for passing load limit bylaws. In place of the MTO review, engineering recommendations to support the load limit and the duration for which it is valid, must now be stamped by two (2) professional engineers.

GHD Limited was retained by the Township of McKellar to inspect a total of seven (7) bridges and two (2) culverts on the Township's road system in 2023 and prioritize the maintenance, repair and replacement works for these structures.

GHD Limited has completed the structure appraisals using WorkTech's Asset Foundation Software.

The procedures used to carry out this 2023 structure inventory are explained in detail in the following manuals published by the Ministry of Transportation and Municipal Engineers Association.

- a. Municipal Bridge Appraisal Manual February 1992
- b. Municipal Culvert Appraisal Manual August 1993
- c. Ontario Structure Inspection Manual 2000 (OSIM) Revised (May 2018)

This report documents the visual inspection and recommendations for the maintenance, repair, or replacement (MR&R) of the structures.

2. Scope and limitations

The assignment included an assessment of seven (7) bridges and two (2) culverts currently identified on the Township of McKellar's road system. The work involved the following tasks:

1. A visual inspection for deficiencies and the recording of any relevant dimensions.
2. An updated photographic inventory of the structure appearance and deficiencies.
3. The compilation of the field review using Worktech Asset Foundation Software.
4. An individual assessment of the condition and state of repair/non-repair of each structure, as well as the recommendation of improvements and estimated costs to bring the existing structures to an acceptable level-of-service.
5. Recommendation of the feasible options and cost-effectiveness of maintaining the existing structure versus possible replacement and the costs and timing of the same.
6. Development of a spreadsheet program to determine various condition and appraisal ratings for each structure. The program includes an algorithm to determine an Overall Condition Rating, Functional Needs Rating and Overall Rating for each structure as outlined in **Appendix D**. Relative rankings of bridge and culvert needs have also been provided.
7. Calculation of the Current Replacement Value (CRV) for each structure.
8. Identification of specific budget recommendations for detailed condition surveys and bridge rehabilitation/replacement including associated engineering design and supervision and construction estimates.

This report: has been prepared by GHD for Township of McKellar and may only be used and relied on by Township of McKellar for the purpose agreed between GHD and Township of McKellar as set out in section 1 of this report.

GHD otherwise disclaims responsibility to any person other than Township of McKellar arising in connection with this report. GHD also excludes implied warranties and conditions, to the extent legally permissible.

The services undertaken by GHD in connection with preparing this report were limited to those specifically detailed in the report and are subject to the scope limitations set out in the report.

The opinions, conclusions and any recommendations in this report are based on conditions encountered and information reviewed at the date of preparation of the report. GHD has no responsibility or obligation to update this report to account for events or changes occurring subsequent to the date that the report was prepared.

The opinions, conclusions and any recommendations in this report are based on assumptions made by GHD described in this report (refer section(s) 4 through 7 of this report). GHD disclaims liability arising from any of the assumptions being incorrect.

3. State of the Infrastructure

3.1 Structure Categorization

The following definitions were used in the preparation of the Bridge and Culvert appraisal reports:

Bridge - In general, transfers all live loads through a superstructure to a substructure and foundations. Bridges that were originally designed as a bridge and have some depth of fill placed over the deck have been inspected as a bridge.

Box or open type structure having less than 600 mm of cover have been inspected as a bridge and those with more than 600 mm of cover have been inspected as a culvert.

Culvert - In general, transfers all live loads through fill.

3.2 Asset Inventory

The Township of McKellar maintains a total of nine (9) structures of 3.0 m span or greater, with an area totalling **983 m²**. **Table 1** below provide a summary of the assets owned by the Township of McKellar. A detailed list of the Township’s overall structure inventory has been provided in **Tables 13 & 14**.

Table 1 Asset Inventory

Asset Category	Count	Area (m ²)	Current Replacement Value (\$Million)
	9	983 m ²	\$14,157,000
Bridge	7	833 m ²	\$11,985,000
Culvert	2	150 m ²	\$2,172,000

3.3 Structure Inventory Replacement Value

Table 2 below provides a conservative estimate of current replacement value on a per structure basis for bridges and culverts. The current replacement value (CRV) is the estimated in-kind replacement cost of each structure. The construction cost of a structure is primarily a function of the size of the structure measured in terms of its span and width and represented by the total deck area (plan area = length x span for culverts). As such, the basic replacement cost of the structure is established using the dimensions of the bridge or culvert and a \$/m² of deck area/plan area unit cost.

Table 2 Structure Replacement Value


Structure Type	Range of Replacement Values	Average Replacement Value
Bridge	\$873,721 - \$3,029,916	\$1,712,108
Culvert	\$1,035,740 - \$1,135,893	\$1,085,816

3.4 Asset Age and Condition

3.4.1 Asset Age

Figure 1 below shows the average age of the Township’s roadway assets against the average estimated useful life, in years, by asset category. The average useful life is based on the design life of the structure extended by appropriately timed maintenance and rehabilitation works. Averages are “weighted” by replacement cost to give more importance to assets with more value to avoid skewing the average asset life with over valuing of small structures.

Figure 1 Asset Life Consumed Profile



4. Structure Inventory and Identification of Maintenance, Repair and Replacement Needs

A total of nine (9) bridge and culvert structures were inspected in 2023. The results of our inspection and recommendations are summarized in the Municipal Bridge and Culvert Appraisal Sheets which are provided in **Appendix E**. A summary of the results of the inspection program for all bridge and culvert structures has been presented in **Appendices B and C**.

Appendix B contains a list of the seven (7) bridges inventoried and appraised while **Appendix C** lists the two (2) culverts.

Based on a review of our inspection findings, recommendations and cost estimates were developed for structures which required maintenance, repair, or replacement as shown in the “Recommended Needs” section of the structure appraisal reports. **Tables B1 and C1** included in **Appendix B** and **Appendix C** summarize basic structure data for all bridge and culvert needs identified through the structure appraisal. The priority ranking of the bridges and culverts based on the results of the Bridge and Culvert Management System are also shown. Of the nine (9) bridge and culvert structures that were appraised in 2023, recommendations are summarized in **Sections 4.1 to 4.5** of this report.

All costs contained within the structure appraisal reports include engineering (15%) and contingencies (20%) and are based on 2023 construction dollars.

4.1 Loading or Dimensional Restrictions

4.1.1 Current Service Performance

The following definitions and methodology were used in the identification of the bridges and culverts with loading and dimensional restrictions as per the Municipal Bridge Appraisal Manual (Feb 1992) and the Municipal Culvert Appraisal Manual (Aug 1993):

Loading Restrictions – Any bridge with an approved municipal bylaw and posting which restricts the gross weight of any vehicle or class of vehicle, which may be a single or triple posting in accordance with the Canadian Highway Bridge Design Code (CHBDC).

4.1.1.1 Load Limit Bylaws

L3 postings govern single unit vehicles; L2 postings govern two-unit vehicles; and L1 postings govern vehicle trains. Section 13 of Bill 92 amends Section 123 of the Highway Traffic Act dealing with the load limit by-laws. Municipalities retain the authority to pass load limit by-laws. Two engineer’s stamps for all load limit by-law recommendations, including load posting and duration, generally 2 years, are required. Load posting assessments are currently being carried out during the annual bridge inspection updates. Load limit recommendations are summarized in **Table 3**.

Table 3 Load Limit Recommendations

Load Limit Recommendations							
Structure No.	Location	Existing Load Limit			Recommended Load Limit		
		L3	L2	L1	L3	L2	L1
-	-	-	-	-	-	-	-

4.2 Engineering Investigations

There is one (1) bridge that has been designated for further engineering investigations to confirm visual repair recommendations as summarized in **Table 4** at a total cost of **\$15,000**. It is recommended that engineering investigations be completed within 2 to 4 years prior to structure rehabilitations.

Table 4 Engineering Investigations

Engineering Investigations					
Structure No.	Location	Recommended Engineering Investigation	Time of Need	Cost for Budget Purposes	Estimated Rehabilitation/Replacement Cost
0004	Hurdville Bridge, Hurdville Road, 6.8 km W of Centre Road	Deck Condition Survey	1-5 yrs	\$15,000	\$658,000

4.3 Structure Removal

- There are no structures recommended for removal at this time, as identified in **Table 5 & 6**.

4.4 Structure Replacements

- There are structures designated for replacement at this time, as identified in **Table 7 & 8**.

4.5 Structure Rehabilitations

- Six (6) bridges require rehabilitation, as identified in **Table 9** at a total cost of **\$1,116,000**. They are presented in order as determined from the Bridge Improvement Priority Program.
- There are no culverts that require rehabilitation at this time, as identified in **Table 10**.
- One (1) bridge requires guide rail installation, extension or upgrades as identified in **Table 11** at a total cost of **\$95,000**.
- Overall structure inventory with priority rankings for all bridge and culverts have been identified in **Table 13 & 14**.

Table 5 Bridge Removal

Bridge Removal - 2023							
Bridge No.	Priority	Location	Reason for Improvement	Estimated Remaining Service Life	Impact of Deferral	Interim Works to Extend Life	Replacement Cost
-	-	-	-	-	-	-	-

Table 6 Culvert Removal

Culvert Removal - 2023							
Culvert No.	Priority	Location	Reason for Improvement	Estimated Remaining Service Life	Impact of Deferral	Interim Works to Extend Life	Replacement Cost
-	-	-	-	-	-	-	-

Table 7 *Bridge Replacements*

Bridge Replacements - 2023								
Bridge No.	Priority	Location	Reason for Improvement	Time of Need	Estimated Remaining Service Life	Impact of Deferral	Interim Works to Extend Life and/or Address Safety Issues	Replacement Cost
-	-	-	-	-	-	-	-	-

Table 8 *Culvert Replacements*

Culvert Replacements - 2023								
Culvert No.	Priority	Location	Reason for Improvement	Time of Need	Estimated Remaining Service Life	Impact of Deferral	Interim Works to Extend Life and/or Address Safety Issues	Replacement Cost
-	-	-	-	-	-	-	-	-

Table 9 Structure Rehabilitations - Bridges

Bridge Rehabilitation Needs by Priority Ranking - 2023						
Bridge No.	Priority	Structure Name	Location	Recommended Work	Time of Need	Rehabilitation Cost
Rehabilitations						
0004	1	Hurdville Bridge	Hurdville Road, 6.80 km W of Centre Road	Repair concrete deck, handrails, curbs, deck soffit, T-beams, piers, abutments, wingwalls, replace deck drain, surface approaches, restore embankments and replace approach guide rail. Should consider replacing barrier system (included in costing).	1-5 yrs	\$643,000
0008	2	Ford Bridge	Broadbent Road, 8.70 km N of Hurdville Road	Repair parapet walls, T-beams, abutments, wingwalls and restore embankments.	1-5 yrs	\$122,000
0005	3	Stewart Park Bridge	Centre Road, 9.80 km S of Highway 124	Install a form and fill groove at the ends of the approach slabs and restore embankments	1-5 yrs	\$29,000
0003	4	Grey Owl Bridge	Grey Owl Road, 2.40 km W of Highway 124	Replace retaining walls and repair abutments	6-10 yrs	\$128,000
0006	5	Broadbent Bridge	Dickinson Road, 0.20 km W of Broadbent Road	Clean and paint structural steel at the abutments and repair deteriorated stringers at abutments	1-5 yrs	\$171,000
0001	6	Veterans Memorial Bridge	Centre Road, 2.70 km E of Highway 124	Repair undermining	6-10 yrs	\$23,000

Table 10 Structure Rehabilitations - Culverts

Culvert Rehabilitation Needs by Priority Ranking - 2023						
Culvert No.	Priority	Structure Name	Location	Recommended Work	Time of Need	Rehabilitation Cost
Rehabilitations						
-	-	-	-	-	-	-

4.5.1 Summary of Now Guide Rail Requirements

Older structures often lack approach guide rail or incorporate approach guide rail systems with buried or terminal ends that are considered to be deficient relative to current standards for end treatments. Additionally, railing systems on older structures often require augmentation with guide rail type systems installed in front of the railings. There is one (1) bridge that requires guide rail installation, extension of upgrades as identified in **Table 11 & 12** at a total cost of **\$95,000**.

Table 11 NOW Guide Rail Requirements - Bridges

Bridge Guide Rail Requirements - 2023					
Bridge No.	Bridge Name	Location	Recommended Work	Time of Need	Estimated Cost
0004	Hurdville Bridge	Hurdville Road, 6.80 km W of Centre Road	Replace approach guide rail	Now	\$95,000

Table 12 NOW Guide Rail Requirements - Culverts

Culvert Guide Rail Requirements - 2023					
Culvert No.	Culvert Name	Location	Recommended Work	Time of Need	Estimated Cost
-	-	-	-	-	-

All guide rail requirement costs provided do not include the potential traffic control costs that may be incurred if the guide rail work is undertaken independent of other necessary works.

Table 13 Overall Bridge Inventory

Bridge Inventory - 2023			
Bridge No.	Priority	Structure Name / Location	Current Replacement Value
0001	6	Veterans Memorial Bridge, Centre Road, 2.70 km E of Highway 124	\$3,029,916
0003	4	Grey Owl Bridge, Grey Owl Road, 2.40 km W of Highway 124	\$873,721
0004	1	Hurdville Bridge, Hurdville Road, 6.80 km W of Centre Road	\$1,642,877
0005	3	Stewart Park Bridge, Centre Road, 9.80 km S of Highway 124	\$2,342,665
0006	5	Broadbent Bridge, Dickinson Road, 0.20 km W of Broadbent Road	\$1,290,300
0007	7	Inholmes Bridge, Broadbent Road, 7.20 km N of Hurdville Road	\$1,589,836
0008	2	Ford Bridge, Broadbent Road, 8.70 km N of Hurdville Road	\$1,215,444

Table 14 Overall Culvert Inventory

Culvert Inventory - 2023			
Culvert No.	Priority	Structure Name / Location	Current Replacement Value
0002	1	Squaw Lake Culvert, Balsam Road, 4.8 km N of Centre Road	\$1,135,893
0010	2	Blackwater Road Culvert, Blackwater Road, 2.0 km S of Hurdville Road	\$1,035,740

4.6 Monitoring

There are no structures at this time that require on-going monitoring to ensure safety and serviceability as presented in **Table 15**.

Table 15 Monitoring

Monitoring		
Structure No.	Location	Monitoring Requirements
-	-	-

5. Structure Inventory and Construction Needs Summary

Tables 16 & 17 which follow provide a summary of the total structure construction and rehabilitation needs resultant from the 2023 structure inspections. For the ten-year period, the rehabilitation needs are estimated to be **\$1,131,000** for the existing Township's structure system. Of this total cost **\$170,000** are for Now needs, **\$810,000** are for structure 1-5 year needs and **\$151,000** are for the 6–10-year needs.

Table 16 Bridge Improvement Needs Summary

Not Adjusted for Owners Share (\$)				
	1-5	6-10	Now	Total
Const	0.00	0.00	0.00	0.00
Const Extra	0.00	0.00	0.00	0.00
Inspection	15,000.00	0.00	0.00	15,000.00
Rehab	436,000.00	82,000.00	149,000.00	667,000.00
Rehab Extra	359,000.00	69,000.00	21,000.00	449,000.00
Total	810,000.00	151,000.00	170,000.00	1,131,000.00

Adjusted for Owners Share (\$)				
	1-5	6-10	Now	Total
Const	0.00	0.00	0.00	0.00
Const Extra	0.00	0.00	0.00	0.00
Inspection	15,000.00	0.00	0.00	15,000.00
Rehab	436,000.00	82,000.00	149,000.00	667,000.00
Rehab Extra	359,000.00	69,000.00	21,000.00	449,000.00
Total	810,000.00	151,000.00	170,000.00	1,131,000.00

Table 17 Culvert Improvement Needs Summary

Not Adjusted for Owners Share (\$)				
	1-5	6-10	Now	Total
Const	0.00	0.00	0.00	0.00
Const Extra	0.00	0.00	0.00	0.00
Inspection	0.00	0.00	0.00	0.00
Rehab	0.00	0.00	0.00	0.00
Rehab Extra	0.00	0.00	0.00	0.00
Total	0.00	0.00	0.00	0.00

Adjusted for Owners Share (\$)				
	1-5	6-10	Now	Total
Const	0.00	0.00	0.00	0.00
Const Extra	0.00	0.00	0.00	0.00
Inspection	0.00	0.00	0.00	0.00
Rehab	0.00	0.00	0.00	0.00
Rehab Extra	0.00	0.00	0.00	0.00
Total	0.00	0.00	0.00	0.00

6. Normal Structure Maintenance

A summary of normal structure maintenance for all bridge and culvert structures has been presented in **Table 18 & 19** (below) as a result of the 2023 inspections. They have been presented in order of Time of Need (TON).

Table 18 Normal Structure Maintenance Summary - Bridges

Bridge Maintenance - 2023			
Bridge No.	Location	Maintenance Requirements	Time of Need
0003	Grey Owl Bridge, Grey Owl Road, 2.40 km W of Highway 124	Regrade approaches, replace damaged sections of guide rail	Now
0005	Stewart Park Bridge, Centre Road, 9.80 km S of Highway 124	Replace missing barrier rail end cap, replace broken/bent handrail post and reposition guide rail posts	Now
0006	Broadbent Bridge, Dickinson Road, 0.20 km W of Broadbent Road	Repair guide rail end treatments	Now
0008	Ford Bridge, Broadbent Road, 8.70 km N of Hurdville Road	Repair approaches, adjust guide rail, replace leaning hazard markers and unplug deck drains	Now

Table 19 Normal Structure Maintenance Summary - Culverts

Culvert Maintenance - 2023			
Culvert No.	Location	Maintenance Requirements	Time of Need
-	-	-	-

7. Recommended Program Funding Levels

Recommended program funding level calculations are typically based on the length of or number of the infrastructure types and average widths of same within the database.

It should be noted that the budgetary recommendations in this report do not include items in the budget related to development and growth. Those items are in addition to the recommendations in this report and should require another funding source.

7.1 Capital Replacements

Recommended funding for the structures inventory would include sufficient capital expenditures that would allow the replacement of infrastructure as it meets its design life.

For new structures, the design lifespan is now 75 years; however, structures constructed prior to 2000 were generally designed for a 50 year lifespan. Accordingly, between 1.5% and 2.0% of the overall current replacement value of the entire structure inventory of **\$14,157,000** should be budgeted annually to ensure that the structure inventory can be maintained in perpetuity. It is noted that as the structures are replaced, the annual allocation could be reduced to 1.5%.

Based on the aforementioned structure inventory replacement value of **\$14,157,000** and the data shown in **Section 3.2** of this report, the estimated minimum annual capital program for structures should be in the amount of **\$269,000** (1.9%) per year for the Township of McKellar to maintain the current system adequacy. However, given the average age of the Township’s structures inventory, it is probable that expenditures on structures will be higher than estimated over the next decade as the older structures reach a terminal condition.

Rehabilitation and replacement recommendations are provided within this report. The costs associated with these recommendations should be budgeted above and beyond the recommended annual capital program. For the ten-year period, the “Not Adjusted for Owners Share” rehabilitation and replacement needs are estimated to be **\$1,131,000** for the existing Township’s structure system. The annual value of **\$113,100** associated with these recommendations should be budgeted above and beyond the recommended annual capital program amount of **\$269,000** as shown above to maximize the service life of the structures. The total forecasted expenditures over ten years are currently valued at **\$382,100** annually.

7.2 Major Maintenance

Rehabilitation and replacement recommendations are provided within this report (**see section 4**). The costs associated within these recommendations should be budgeted above and beyond the recommended replacement budget suggested in **Section 7.1** to maximize the service life of the structures.

8. Conclusion

Completion of the 2023 re-inspection of seven (7) bridges and two (2) culverts on the Township's road system has resulted in reliable and current data being available to the Township to implement a maintenance program ensuring the Township's structures are kept safe and in good repair.

Maintenance of the Bridge and Culvert Management Program will require updating of the database on an on-going annual basis to reflect previous year rehabilitation/replacement project updates. It is recommended that the structures be re-inspected by a qualified structure engineer every two (2) years.



We trust that the foregoing will assist you in implementing a cost-effective structure maintenance, repair, and replacement program.

Appendices

Type text here


Appendix A

Key Plan



Legend

- Bridge (With Inventory No.)
- Culvert (With Inventory No.)
- Provincial Highway
- Major Road
- Local Road
- Waterbody
- Watercourse
- Municipal Boundary



© 2019. Whilst every care has been taken to prepare this map, GHD (and R. Galos) make no representations or warranties about its accuracy, reliability, completeness or suitability for any particular purpose and cannot accept liability and responsibility of any kind (whether in contract, tort or otherwise) for any expenses, losses, damages and/or costs (including indirect or consequential damage) which are or may be incurred by any party as a result of the map being inaccurate, incomplete or unsuitable in any way and for any reason.

PROJECT: 2023 STRUCTURE INSPECTIONS
 DRAWING: STRUCTURE LOCATIONS



PREPARED BY: R. GALOS	CHECKED BY: W. BALDIN	PROJECT: 12604686
DESIGNED BY: ---	APPROVED BY: J. PARKINSON	MAP: 1
SCALE: 1:56,000	DATE: April 2023	

Appendix B

Bridge Improvement Needs

Township of McKellar Bridge Improvement Needs

Bridge No.	Priority	Bridge Name	Road Name	Location	Const. Yr Sub/ Super	Ex. Load Posting			Crossing Type	No. of Spans	Deck Length (m)	Deck Width (m)	Eng. Invest. Type/ Cost (\$)	Improvement Recommendations			
						L3t	L2t	L1t						Category	Type	TON	Cost(1)
0004	1.00	Hurdville Bridge	Hurdville Road	6.80 km W of Centre Road	1930 1930	0	0	0	O-WAT, Over	4	24.40	5.00	DCS 15,000	Rehab	IAG	NOW	95,000
													Rehab	RIR	NOW	54,000	
													Rehab Extra	brMB	NOW	7,000	
													Rehab Extra	brTCP	NOW	14,000	
													Total Cost NOW			170,000	
													Rehab	CDS	1-5	20,000	
													Rehab	EIR	1-5	68,000	
													Rehab	RCS	1-5	14,000	
													Rehab	RSB	1-5	122,000	
													Rehab	RSP	1-5	27,000	
													Rehab	WSR	1-5	14,000	
													Rehab Extra	brAPP	1-5	68,000	
													Rehab Extra	brENV	1-5	20,000	
													Rehab Extra	brMB	1-5	11,000	
													Rehab Extra	brTCP	1-5	14,000	
													Rehab Extra	brWPTF	1-5	41,000	
													Rehab Extra	UNW	1-5	54,000	
													Total Cost 1-5			473,000	
													Total Cost			643,000	
													Municipal %			100	
													MunicipalCost			643,000	

Notes:
 1. Cost includes engineering and contingency allowances.
 2. Total cost includes cost of engineering investigations. Total cost is not adjusted for owner share.

Bridge No.	Priority	Bridge Name	Road Name	Location	Const. Yr Sub/ Super	Ex. Load Posting			Crossing Type	No. of Spans	Deck Length (m)	Deck Width (m)	Eng. Invest. Type/ Cost (\$)	Improvement Recommendations				
						L3t	L2t	L1t						Category	Type	TON	Cost(1)	
0008	2.00	Ford Bridge	Broadbent Road	8.70 km N of Hurdville Road	1930 1930	0	0	0	O-WAT, Over	1	13.10	5.70		Maintenance	OTH	NOW	0	
														Total Cost NOW				0
														Rehab	EIR	1-5	20,000	
														Rehab	RIR	1-5	14,000	
														Rehab	RSB	1-5	14,000	
														Rehab	RSP	1-5	20,000	
														Rehab Extra	brMB	1-5	6,000	
														Rehab Extra	brTCP	1-5	14,000	
														Rehab Extra	brWPTF	1-5	34,000	
														Total Cost 1-5				122,000
Total Cost				122,000														
Municipal %				100														
MunicipalCost				122,000														
0005	3.00	Stewart Park Bridge	Centre Road	9.80 km S of Highway 124	1992 1992	0	0	0	O-WAT, Over	1	21.00	9.40		Maintenance	OTH	NOW	0	
														Total Cost NOW				0
														Rehab	EIR	1-5	14,000	
														Rehab Extra	brAPP	1-5	7,000	
														Rehab Extra	brMB	1-5	1,000	
														Rehab Extra	brTCP	1-5	7,000	
														Total Cost 1-5				29,000
														Total Cost				29,000
														Municipal %				100
														MunicipalCost				29,000
0003	4.00	Grey Owl Bridge	Grey Owl Road	2.40 km W of Highway 124	1984 1984	0	0	0	O-WAT, Over	1	7.00	5.10		Maintenance	OTH	NOW	0	
														Total Cost NOW				0
														Rehab	RRW	6-10	54,000	
														Rehab	RSB	6-10	14,000	
														Rehab Extra	brENV	6-10	10,000	
														Rehab Extra	brMB	6-10	2,000	
														Rehab Extra	brTCP	6-10	14,000	
														Rehab Extra	UNW	6-10	34,000	
														Total Cost 6-10				128,000
														Total Cost				128,000
Municipal %				100														
MunicipalCost				128,000														

- Notes:**
1. Cost includes engineering and contingency allowances.
 2. Total cost includes cost of engineering investigations. Total cost is not adjusted for owner share.

Bridge No.	Priority	Bridge Name	Road Name	Location	Const. Yr Sub/Super	Ex. Load Posting			Crossing Type	No. of Spans	Deck Length (m)	Deck Width (m)	Eng. Invest. Type/ Cost (\$)	Improvement Recommendations			
						L3t	L2t	L1t						Category	Type	TON	Cost(1)
0006	5.00	Broadbent Bridge	Dickinson Road	0.20 km W of Broadbent Road	1910 2008	0	0	0	O-WAT, Over	1	17.30	4.10		Maintenance	OTH	NOW	0
														Total Cost NOW			0
														Rehab	CSS	1-5	81,000
														Rehab	RSP	1-5	8,000
														Rehab Extra	brDET	1-5	14,000
														Rehab Extra	brENV	1-5	20,000
														Rehab Extra	brMB	1-5	7,000
Rehab Extra	brWPTF	1-5	41,000														
Total Cost 1-5			171,000														
Total Cost			171,000														
Municipal %			100														
MunicipalCost			171,000														
0001	6.00	Veterans Memorial Bridge	Centre Road	2.70 km E of Highway 124	2010 2010	0	0	0	O-WAT, Over	1	25.90	9.10		Rehab	EIR	6-10	14,000
														Rehab Extra	brMB	6-10	2,000
														Rehab Extra	brTCP	6-10	7,000
														Total Cost 6-10			23,000
Total Cost			23,000														
Municipal %			100														
MunicipalCost			23,000														
0007	-	Inholmes Bridge	Broadbent Road	7.20 km N of Hurdville Road	1920 2023	0	0	0	O-WAT, Over	2	19.55	4.93					

Total Cost of Recommended Improvements

(2)

- Notes:**
1. Cost includes engineering and contingency allowances.
 2. Total cost includes cost of engineering investigations. Total cost is not adjusted for owner share.

BRIDGE IMPROVEMENT NEEDS

The bridges of span 3.0 m and greater under the jurisdiction of the Township of McKellar which were inventoried and appraised are listed in the following table. The bridge inventory section table is arranged numerically by bridge number and provides the following information:

- Local bridge number
- Priority Ranking
- The bridge name
- The bridge locations
- The year of substructure and superstructure construction
- Existing Load Limit Postings
- The crossing type
- The number of spans
- The deck length and deck width
- The requirement for any engineering investigation, year and cost
- The recommended type and time of improvement
- The construction cost of the recommended improvement and the total project cost including engineering and contingency allowances

The following abbreviations are used in Table B1:

bc - Bridge Construction

br - Bridge Rehabilitation

Crossing Type

O-WAT - Over Water

U-RWY - Under Railway

O-RWY - Over Railway

Engineering Investigations

SEI – Seismic Investigation

UI – Underwater Investigation

RDI - Routine Detailed Inspection

STI - Structure Investigation

RRA - Rehabilitate/Replace Analysis

LCE – Load Capacity Evaluation

C/S - Condition Survey of Other Components

C/I - Condition Inspection

DART - DART Survey

DCCS - Detail Coating Condition Survey
DCS - Deck Condition Survey
FI - Fatigue Investigation
GEOMOR - Geomorphic Investigation
GEOTEC - Geotechnical Investigation

Type of Improvements

Capital Improvements / Construction Extra

NEW - New Bridge
RBC - Replace Bridge with Culvert
REB - Remove Existing Bridge
RNL - Replace Bridge - New location
RSL – Replace Bridge Same Location
TEB – Twin Existing Bridge
bcApp - Approaches
bcTCP - Traffic Control / Protection
bcUTI - Utility Relocation
bcROW - Right of Way Costs
bcENV - Environmental Study Cost
bcDET - Detours
bcMOB - Mobilization
bcWPTF – Work Platform / Access
brUNW - Unwatering

Bridge Rehabilitation Improvements / Rehabilitation Extra

RSP - Rehabilitate Superstructure
RSB - Rehabilitate Substructure
RRW - Rehabilitate/Replace Retaining Walls
RIR - Railing Improvement/Replacement

Deck Rehabilitation Improvements

WSR - Wearing Surface Rehabilitation
CDR - Complete Deck Replacement
OWP - Overlay, Waterproof and Pave
PWP - Patch, Waterproof and Asphalt Paving

CDS - Concrete Deck Soffit Repairs
CR - Concrete Repairs
PDR - Partial Deck Replacement
RCS - Rehabilitation/Replacement of Safety Curbs/Sidewalk
TJM - Transverse Exp Joint Modification
TJR - Transverse Expansion Joint Replacement
TJS - Transverse Expansion Joint Seal Replacement
LMC - Latex Modified Concrete Overlay
LJM - Longitudinal Exp Joint Modification
LJR - Longitudinal Exp Joint Replacement
LJS - Longitudinal Exp Joint Seal Replacement

Bridge Coating Improvements

CSR - Coating Steel Railings
CSS - Coating Structural Steel

Stream/Waterway Improvements

SPI - Scour Protection Improvements
C/I - Channel Improvements
C/R - Channel Realignment
EIR - Embankment Improvement/Rehab

Safety Improvements

IAG - Installation of Approach Guide rail
IAB - Install Approach Safety Shape Barrier

Non Standard Improvements

OTHm - Maintenance Improvements
OTHr - Rehabilitation Improvements

Costing Category

PC - Preliminary Cost Estimate

Appendix C

Culvert Improvement Needs

Township of McKellar Culvert Improvement Needs

Culvert No.	Priority	Culvert Name	Road Name	Location	Const Yr	Ex. Load Posting			Crossing Type	No. of Cells	Total Span (m)	Culvert Length (m)	Eng. Invest. Type/ Cost (\$)	Improvement Recommendations				
						L3t	L2t	L1t						Category	Type	TON	Cost(1)	
0002	-	Squaw Lake Culvert	Balsam Road	4.8 km N of Centre Road	1982	0	0	0	O-WAT, Over	1	6.10	13.80						
0010	-	Blackwater Road Culvert	Blackwater Road	2.0 km S of Hurdville Road	2017	0	0	0	O-WAT, Over	1	4.37	15.00						

Total Cost of Recommended Improvements

(2)

Notes:
 1. Individual item costs include engineering and contingency allowances.
 2. Total cost includes cost of engineering investigations. Total cost is not adjusted for owner share.

CULVERT IMPROVEMENT NEEDS

The culverts of span 3.0 m and greater under the jurisdiction of the Township of McKellar which were inventoried and appraised are listed in the following table. The culvert inventory section table is arranged numerically by culvert number and provides the following information:

- Local culvert number
- Priority ranking
- The culvert name
- The culvert road name
- The culvert location
- The year of construction
- The year extended
- Load limit postings
- The crossing type
- The number of cells
- The total span in metres
- The culvert length
- The requirement for any engineering investigation, year and cost
- The recommended type and time of improvement
- The construction cost of the recommended improvement and the total project cost including engineering and contingency allowances

The following abbreviations are used in Table C1:

c - Culvert

cc - Culvert Construction

cr - Culvert Rehabilitation

Crossing Type

O-WAT - Over Water

O-PED - Over Pedestrian Walkway

Culvert Type

CPS-PA/ - Corrugated Plate Steel Pipe Arch

CPS-PR/ - Corrugated Plate Steel Pipe Round

CPS-PAS - Corrugated Plate Steel Pipe Arch with Stiffener and/or Buttress

CPS-PHS - Corrugated Plate Steel Pipe Horizontal Ellipse with Stiffener and/or Buttress

CPS-PHE - Corrugated Plate Steel Pipe Horizontal Ellipse

CPR-OTH - Cast-in-Place Reinforced Concrete Other

CPR-BOX - Cast-in-Place Reinforced Concrete Box

CPR-FRA - Cast-in-Place Replacement Concrete Frame

PCC-PR/ - Precast Concrete Pipe Round

CST-PA/ - Corrugated Steel Pipe Arch

CST-PR/ - Corrugated Steel Pipe Round

Engineering Investigations

cUI – Underwater Investigation

cRDI - Routine Detailed Inspection

cRRA - Rehabilitate/Replace Analysis

cLCE – Load Capacity Evaluation

cC/S - Condition Survey of other Components

cC/I - Condition Inspection

cENV - Environmental Study Cost

cGEOMOR - Geomorphic Investigation

cGEOTEC - Geotechnical Investigation

Type of Improvements

Capital Improvements / Construction Extra

cREC - Remove Existing Culvert

cRSL - Replace Culvert, Same Location

ccAPP - Approaches

ccDET - Detours

ccTCP - Traffic Control / Protection

ccUTI - Utility Relocation

ccROW - ROW Costs

ccENV - Environmental Study

ccMOB - Mobilization

ccWPTF – Work Platform / Access

ccUNW - Unwatering

Rehabilitation Improvements / Rehabilitation Extra

cRRW - Rehabilitate/Replace Retaining Walls/Wingwalls

cRSP - Rehabilitate Superstructure

cRSB - Rehabilitate Substructure

cRIO - Rehabilitate Inlet/Outlet Treatment

cRCF - Rehabilitate Culvert Floor/Invert

crAPP - Approaches

crDET - Detours

crTCP - Traffic Control / Protection

crUTI - Utility Relocation

crROW - ROW Costs

crENV - Environmental Study

Stream/Waterway Improvements

cEIR - Embankment Improvements/Rehabilitation

cSPI - Scour Protection Improvements

cC/R - Channel Realignment

cCH/I - Channel Improvements

Safety Improvements

clAG - Installation of Approach Guide Rail

Costing Category

cPC - Preliminary Cost Estimate

Appendix D

Bridge and Culvert Management Program

BRIDGE AND CULVERT MANAGEMENT SYSTEM

In order to provide the Township of McKellar with a means to evaluate future maintenance, repair and replacement needs based on updated inspection information, a Bridge & Culvert Management System was developed. The results produced by the program were determined from the following input data for each structure:

- Bridge (or Culvert) Needs ratings (MCR and PCR) identified in Section G of the Municipal Bridge (or Culvert) Appraisal Sheets.
- Functional needs identified in Section H of the Municipal Bridge (or Culvert) Appraisal Sheets.
- Load posting.
- Vehicular traffic at the structure site (AADT).

The following discusses the methodology used in the Bridge & Culvert Management System to determine various condition and appraisal ratings:

Material Condition and Performance Condition Ratings (MCR & PCR) in Section G of the Appraisal reports for bridges and culverts have been input for each structure. The Ontario Structure Inspection Manual (published by the Ministry of Transportation, Ontario), requires that inspectors assign condition ratings from 1 to 6 with 6 representing the best condition as identified below in **Table 20**. Additional ratings of 9, 0 and Y may also be used.

Table 20 Material Condition and Performance Condition Ratings (MCR & PCR)

MCR & PCR RATINGS	RATING VALUE
6 – Very Good	6
5 – Satisfactory	5
4 – Fair	4
3 – Poor	3
2 – Inadequate – urgent	2
1 – Inadequate - critical	1
9 - Component cannot be inspected	6
0 - Component does not exist; Need does not exist	6
Y - Component does not exist; Need exists	1.5

The Functional Needs information is included in Section H of the Municipal Bridge and Culvert Appraisal sheets. In cases where data is missing, the program assumes values. Rating values are determined by comparing the Existing Condition information with the Minimum Tolerable requirement. **Table 21** presents the ratings assigned by the program for bridges, when the Existing Condition is worse than the Minimum Tolerable. **Table 22** presents the assigned rating values for culverts.

Table 21 Functional Needs Ratings for Bridges

Functional Needs	Ratings	
	If Adequate	If Not Adequate
Road Over		
Travel Deck Width	6	2
Level of Service	6	2
Min.Vert. Clearance	6	1
Sidewalks	6	2

Functional Needs	Ratings	
Road Under		
Surface Width	6	2
Level of Service	6	2
Min.Vert. Clearance	6	1
Sidewalks	6	2

Table 22 Functional Needs Ratings for Culverts

Functional Needs	Ratings	
	If Adequate	If Not Adequate
Road Over		
Platform Width	6	2
Level of Service	6	2
Roadside Safety	6	1
Road Through		
Surface Width	6	2
Level of Service	6	2
Min Vertical Clearance	6	1
Sidewalks	6	2

For each rated structural component, an Overall Component Condition Rating is calculated by the program, using the following weight factors for the input MCR and PCR as shown in **Table 23**.

Table 23 Overall Component Condition Rating Weights

Overall Component Condition Rating Weights	
MCR	0.4
PCR	0.6

Load Posting Ratings are assigned using the following comparisons, as shown in **Table 24**.

Table 24 Load Posting Ratings

Condition	Assigned Load Posting Rating
If Load Posting is greater than 20 tonnes	6
If Load Posting >18 tonnes and # 20 tonnes	5
If Load Posting >16 tonnes and # 18 tonnes	4.5
If Load Posting >14 tonnes and # 16 tonnes	4
If Load Posting >12 tonnes and # 14 tonnes	3
If Load Posting >10 tonnes and # 12 tonnes	2
If Load Posting # 10 tonnes	1

Appendix E

Structure Appraisal Reports

MUNICIPAL BRIDGE APPRAISAL

A. IDENTIFICATION

Bridge Name: Veterans Memorial Bridge	Bridge No.: 0001
Road Name: Centre Road	Road Section No.
Location: 2.70 km E of Highway 124	MTO Site No.: 044-0083-
Roadside Env.: R	Posting Sign: t t t
BL Posting: t t t	Low Clear Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 586843
Bylaw Exp. Date:	Northing: 5040449
	Crossing Type: O-WAT, Over Water
	Federal Navigable Waterway: Yes
	Bridge Value: \$ 3,030,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage:	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Bridge No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Substructure Yr: 2010	Span Length: 23.0 m	Longitudinal Joints: 0
Superstructure Yr: 2010	Deck Type: CC - Concrete, Cast in Place	Transverse Joints: 0
Bridge Type: W - IB - S	Deck Length: 25.9 m	Number of Bearings: 8
Crossing Skew: -00 °	Deck Width: 9.1 m	Soil Condition: U
Number of Spans: 1	Deck Area: 235.7 m ²	Abutment and Foundation Type: Closed - PC

ROAD OVER BRIDGE

Existing Road Class: 200	No. of Lanes: 2.0	Barrier Walls/Railings: CP
Operational Status: 2W - OAT	Median Type/Width: m	Min Vertical Clearance: m
Wearing Surface: A	Safety Curb/ (A) N E 0.0 m	
Travel Deck Width: 8.50 m	Sidewalk and Curb (B) N / W 0.0 m	

ROAD UNDER BRIDGE

Existing Road Class:	No. of Lanes:	Traffic Barrier:
Operational Status: -	Median Type/Width: m	Min Vertical Clearance: m
Opening Under: m	Safety Curb/ (A) m	
Surface Width: m	Sidewalk and Curb (B) / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 100	AADT: 110
<input checked="" type="checkbox"/> School <input type="checkbox"/> Bike Route	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Bridge 0001 Asset Master	10 Year Growth Factor: 1.10	20 Year AADT: 121

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Bridge No.: 0001

MUNICIPAL BRIDGE APPRAISAL

G. BRIDGE NEEDS

Field	MCR	PCR	TON	Comments
Superstructure	5	6	6-10	
Wearing Surface	5	5	6-10	
Deck Condition	5	6	6-10	
Expansion Joints	0	0	ADEQ	
Railings	5	6	6-10	
Substructure	5	6	6-10	
Coating	6	6	ADEQ	
Streams/Waterways	5	5	6-10	
Curb/Sidewalk	0	0	ADEQ	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Bridge				
RO-Trav. Deck Width	8.5	6.5	ADEQ	Proj Class: 200, 110 (10 YR, 100*1.1)
RO-LOS	A	E	ADEQ	
RO-Min. Vertical Clear.		4.5	ADEQ	No value for: Min Vertical Clearance
RO-Sidewalks	N	N	ADEQ	

Recommended Needs

Impr.Class	Improvement	Description	Time of Need	Year	Base/ Const Cost	Eng/Cont	Total
Rehab	EIR	Embankment Improvement/Rehab	6-10	0	10,000	4,000	14,000
					Rehab Subtotal:	10,000	4,000
Rehab Extra	brMB	Mobilization / Bonds / Permits	6-10	0	2,000	0	2,000
Rehab Extra	brTCP	Traffic Control/Protection	6-10	0	5,000	2,000	7,000
					Rehab Extra Subtotal:	7,000	2,000
						9,000	9,000

I. ENGINEERING RECOMMENDATIONS

Bridge Drawings:
 Estimated Posting: t
 Evaluated Posting: t t t
 Closure Date:
 Closure Type:
 Monitoring Interval:
 Monitoring Component:

J. DESIGN PARAMETERS

Design Class:
 Operational Status: -
 Abutment Type:
 Design Deck Width:
 Design Deck Length:

K. IMPROVEMENT COSTS

Total Construction/Rehab	23,000
Total Inspection	0
TOTAL	23,000
86613 share @100%	23,000

INSPECTION NOTES

Bridge No.: 0001

Bridge No. 0001, Veterans Memorial Bridge, Centre Road, Lot 22, Concession XI, 2.70 km South of Highway 124, Township of McKellar:

- Structure is not posted with a load limit.
- 23m +/- single span weathering steel girder bridge with a concrete deck and asphalt wearing surface.
- Concrete parapet walls are in generally good condition with light abrasions on the Northeast and Southwest end posts, narrow stained and unstained cracks, hairline stained map cracking, light scaling.
- Steel handrailings over parapet walls are in generally good condition with 4 missing bolts, loose railing on South side, 3 posts exhibit collision damage.
- Asphalt deck wearing surface is in generally good condition with light ravelling, sealed cracks and narrow cracks.
- Concrete deck soffit is in good condition.
- Concrete fascias are in generally good condition with narrow stained cracks and surface rust stains.
- Steel girders are in generally good condition with large deflection noted, light flaking of patina, birds nests and deflection noted (reverse camber).
- Ends of girders are coated and are in good condition with several birds nests noted.
- Elastomeric bearings are in generally good condition with loss of contact (<5%) noted at all bearings on the west abutment and two bearings on east abutment, minor bulging and unevenly loaded bearings at the west end.
- Concrete abutments are in generally good condition with narrow cracks on the ballast wall and surface rust stains.
- Concrete wingwalls are in generally good condition with surface rust stains and wet areas.
- Steel beam guide rails are in generally good condition with minor collision damage. Moderate collision damage to the channel at the Southeast.
- Eccentric loader end treatments are provided in all four quadrants and are in good condition.
- Vegetated and gravel embankments are in good condition. Moderate undermining of the wingwall at the Northwest.
- Watercourse is unobstructed with no evidence of scour.
- Gabion basket retaining walls are provided in all quadrants except the southwest and are in good condition.
- Asphalt approach wearing surface is in generally good condition with light ravelling and minor settlement beyond the approaches.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.
- Should repair undermining.

L. HISTORY/ GENERAL

Bridge No.: 0001



Comments: LOOKING WEST AT BRIDGE

Path: P:\McKellar\2023\P1080126.jpg



Comments: LOOKING EAST AT BRIDGE

Path: P:\McKellar\2023\P1080127.jpg



Comments: NORTH ELEVATION

Path: P:\McKellar\2023\P1080128.jpg



Comments: SOUTH ELEVATION

Path: P:\McKellar\2023\P1080129.jpg



Comments: COLLISION DAMAGE APPROACH GUIDE RAIL

Path: P:\McKellar\2023\P1080130.jpg



Comments: TYPICAL WEARING SURFACE

Path: P:\McKellar\2023\P1080131.jpg



Comments: NARROW TRANSVERSE CRACK IN WEARING SURFACE
Path: P:\McKellar\2023\P1080132.jpg



Comments: NARROW TRANSVERSE CRACK IN WEARING SURFACE
Path: P:\McKellar\2023\P1080149.jpg



Comments: COLLISION DAMAGE PARAPET HAND RAILING
Path: P:\McKellar\2023\P1080133.jpg



Comments: MISSING BOLT PARAPET HAND RAILING
Path: P:\McKellar\2023\P1080134.jpg



Comments: NARROW STAINED CRACK IN INTERIOR PARAPET WALL

Path: P:\McKellar\2023\P1080135.jpg



Comments: ABRASION PARAPET END POST

Path: P:\McKellar\2023\P1080136.jpg



Comments: TYPICAL WEST ABUTMENT

Path: P:\McKellar\2023\P1080138.jpg



Comments: TYPICAL EAST ABUTMENT

Path: P:\McKellar\2023\P1080139.jpg



Comments: TYPICAL ABUTMENT BEARING
Path: P:\McKellar\2023\P1080137.jpg



Comments: MINOR LOSS OF CONTACT ABUTMENT BEARING
Path: P:\McKellar\2023\P1080146.jpg



Comments: NARROW VERTICAL CRACK EAST ABUTMENT
Path: P:\McKellar\2023\P1080151.jpg



Comments: NARROW VERTICAL CRACK EAST BALLAST WALL
Path: P:\McKellar\2023\P1080152.jpg



Comments: TYPICAL SOFFIT
Path: P:\McKellar\2023\P1080140.jpg



Comments: NARROW STAINED CRACK EXTERIOR SOFFIT
Path: P:\McKellar\2023\P1080147.jpg



Comments: REVERSE CAMBER ON EXTERIOR GIRDER
Path: P:\McKellar\2023\P1080143.jpg



Comments: NARROW STAINED CRACK EXTERIOR PARAPET WALL
Path: P:\McKellar\2023\P1080148.jpg



Comments: WATER STAINING ON WINGWALL

Path: P:\McKellar\2023\P1080150.jpg



Comments: MODERATE UNDERMINING BELOW WINGWALL

Path: P:\McKellar\2023\P1080145.jpg



Comments: WATERCOURSE UNDER BRIDGE
Path: P:\McKellar\2023\P1080141.jpg



Comments: LOOKING SOUTH DOWNSTREAM
Path: P:\McKellar\2023\P1080142.jpg



Comments: LOOKING NORTH UPSTREAM
Path: P:\McKellar\2023\P1080144.jpg

Comments:
Path:

MUNICIPAL BRIDGE APPRAISAL

A. IDENTIFICATION

Bridge Name: Grey Owl Bridge	Bridge No.: 0003
Road Name: Grey Owl Road	Road Section No.
Location: 2.40 km W of Highway 124	MTO Site No.: 044-0219-
Roadside Env.: R	Posting Sign: t t t
BL Posting: t t t	Low Clear Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 582370
Bylaw Exp. Date:	Northing: 5042218
	Crossing Type: O-WAT, Over Water
	Federal Navigable Waterway:
	Bridge Value: \$ 874,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage: 0.00	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Bridge No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Substructure Yr: 1984	Span Length: 5.9 m	Longitudinal Joints: 0
Superstructure Yr: 1984	Deck Type: TL - Transverse Lam. Timber	Transverse Joints: 0
Bridge Type: S - IB - S	Deck Length: 7.0 m	Number of Bearings: 0
Crossing Skew: -00 °	Deck Width: 5.1 m	Soil Condition: U
Number of Spans: 1	Deck Area: 35.7 m ²	Abutment and Foundation Type: Closed - SF

ROAD OVER BRIDGE

Existing Road Class: 100	No. of Lanes: 1.0	Barrier Walls/Railings: FB
Operational Status: 2W - OAT	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Wearing Surface: T	Safety Curb/ (A) N 0.2 m	
Travel Deck Width: 4.70 m	Sidewalk and Curb (B) N / S 0.2 m	

ROAD UNDER BRIDGE

Existing Road Class:	No. of Lanes: 0	Traffic Barrier:
Operational Status: -	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Opening Under: m	Safety Curb/ (A) m	
Surface Width: m	Sidewalk and Curb (B) / m	

E. TRAFFIC DATA

Legal Speed Limit: 40	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 10	AADT: 10
<input type="checkbox"/> School <input type="checkbox"/> Bike Route	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Bridge 0003 Asset Master	10 Year Growth Factor: 1.00	20 Year AADT: 10

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Bridge No.: 0003

MUNICIPAL BRIDGE APPRAISAL

G. BRIDGE NEEDS

Field	MCR	PCR	TON	Comments
Superstructure	5	5	6-10	
Wearing Surface	4	5	1-5	
Deck Condition	4	5	1-5	
Expansion Joints	0	0	ADEQ	
Railings	5	5	6-10	
Substructure	5	5	6-10	
Coating	0	0	ADEQ	
Streams/Waterways	5	5	6-10	
Curb/Sidewalk	5	5	6-10	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Bridge				
RO-Trav. Deck Width	4.7	6.5	NOW	
RO-LOS	A	E	ADEQ	
RO-Min. Vertical Clear.		4.5	ADEQ	No value for: Min Vertical Clearance
RO-Sidewalks	N	N	ADEQ	

Recommended Needs

Impr.Class	Improvement	Description	Time of Need	Year	Base/ Const Cost	Eng/Cont	Total
Maintenance	OTH	Maintenance Improvement	NOW	0	0	0	0
			Maintenance Subtotal:		0	0	0
Rehab	RRW	Rehabilitate /Replace Retaining Walls	6-10	0	40,000	14,000	54,000
Rehab	RSB	Rehabilitate Substructure	6-10	0	10,000	4,000	14,000
			Rehab Subtotal:		50,000	18,000	68,000
Rehab Extra	brENV	Environmental Study Costs	6-10	0	10,000	0	10,000
Rehab Extra	brMB	Mobilization / Bonds / Permits	6-10	0	2,000	0	2,000
Rehab Extra	brTCP	Traffic Control/Protection	6-10	0	10,000	4,000	14,000
Rehab Extra	UNW	Unwatering	6-10	0	25,000	9,000	34,000
			Rehab Extra Subtotal:		47,000	13,000	60,000

I. ENGINEERING RECOMMENDATIONS

Bridge Drawings:

Estimated Posting: t

Evaluated Posting: t t t

Closure Date:

Closure Type:

Monitoring Interval:

Monitoring Component:

J. DESIGN PARAMETERS

Design Class:

Operational Status: -

Abutment Type:

Design Deck Width:

Design Deck Length:

K. IMPROVEMENT COSTS

Total Construction/Rehab	128,000
Total Inspection	0
TOTAL	128,000
86613 share @100%	128,000

INSPECTION NOTES

Bridge No.: 0003

Bridge No. 0003, Grey Owl Bridge, Grey Owl Road, Lot 31, Concession XIV, 2.40 km West of Highway 124, Township of McKellar:

- Structure is not posted with a load limit.
- 5.9 m+- single span structural steel girder bridge with a timber deck.
- Steel guide rail on steel posts provided over the deck and on the approaches. Terminal end treatments provided in all four quadrants. Minor collision damage and a small tear at the Southeast.
- Timber curbs are in generally good condition and have recently been replaced. Curbs exhibit light checks and abrasions.
- Transverse timber deck is in generally good condition with light to medium wear and localized severe wear, wheel track rutting, minor rotation of boards at the east end, water ponding and localized light to severe splits on the ends and protruding nails at the west end.
- Structural steel girders are in generally good condition with light to severe flaking of patina, light to medium pitting. The girders are bearing on the back crib members, loss of contact at abutment crib.
- Pressure treated timber crib abutments are in generally good condition with light to severe checks and splits and light to medium rot at the waterline of both abutment cribs (2.0m², poor). It is noted that rock within the timber crib abutments is only placed to mid height.
- Gabion basket retaining walls are provided in all four quadrants of the structure and are in generally fair to good condition with loss of fill at the bottom baskets due to severe corrosion. Some outward movement was noted at base of Northwest quadrant.
- Embankment slopes are in good condition.
- Gravel approach roads are in generally good condition with light potholes.
- Watercourse is unobstructed with no evidence of scour.
- Hazard markers provided in all four quadrants.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.
- Should replace retaining walls and repair abutments.
- Should regrade approaches, replace damaged sections of guide rail as part of regular structure maintenance.
- Not costed for replacement for travel deck width deficiency due to low traffic volume.

L. HISTORY/ GENERAL

Bridge No.: 0003

Year: 2016, IAG Install Approach Guiderail, Est Cost: 0

Year: 2016, RCS Rehabilitation/Replacement of safety curbs, Est Cost: 0



Comments: LOOKING WEST AT BRIDGE

Path: P:\McKellar\2023\P1080096.jpg



Comments: LOOKING EAST AT BRIDGE

Path: P:\McKellar\2023\P1080097.jpg



Comments: SOUTH ELEVATION

Path: P:\McKellar\2023\P1080098.jpg



Comments: NORTH ELEVATION

Path: P:\McKellar\2023\P1080099.jpg



Comments: LIGHT POTHOLE IN EAST APPROACH

Path: P:\McKellar\2023\P1080105.jpg



Comments: TEAR IN GUIDE RAIL ON APPROACH

Path: P:\McKellar\2023\P1080106.jpg



Comments: TYPICAL WEARING SURFACE

Path: P:\McKellar\2023\P1080100.jpg



Comments: MEDIUM WHEEL TRACK RUTTING IN TIMBER DECK

Path: P:\McKellar\2023\P1080102.jpg



Comments: PROTRUDING NAILS IN TIMBER DECK MEMBERS

Path: P:\McKellar\2023\P1080103.jpg



Comments: LOCALIZED SEVERE ROT OF TIMBER DECK MEMBER

Path: P:\McKellar\2023\P1080104.jpg



Comments: SEVERE WEATHERING OF TIMBER DECK MEMBERS

Path: P:\McKellar\2023\P1080107.jpg



Comments: ROTATION OF TIMBER DECK MEMBERS EAST APPROACH

Path: P:\McKellar\2023\P1080108.jpg



Comments: SEVERE SPLIT IN TIMBER DECK MEMBER EAST APPROACH

Path: P:\McKellar\2023\P1080109.jpg



Comments: MINOR ABRASION IN TIMBER CURB

Path: P:\McKellar\2023\P1080101.jpg



Comments: TYPICAL WEST ABUTMENT

Path: P:\McKellar\2023\P1080110.jpg



Comments: TYPICAL EAST ABUTMENT

Path: P:\McKellar\2023\P1080121.jpg



Comments: TYPICAL SOFFIT

Path: P:\McKellar\2023\P1080113.jpg



Comments: MEDIUM ROT OF TIMBER CRIB MEMBER

Path: P:\McKellar\2023\P1080111.jpg



Comments: MEDIUM ROT OF TIMBER CRIB MEMBERS EAST ABUTMENT

Path: P:\McKellar\2023\P1080112.jpg



Comments: MEDIUM ROT OF TIMBER CRIB MEMBERS WEST ABUTMENT

Path: P:\McKellar\2023\P1080120.jpg



Comments: SEVERE CHECK IN TIMBER CRIB MEMBER
Path: P:\McKellar\2023\P1080124.jpg



Comments: SEVERE FLAKING OF STEEL BALLAST WALL WEST ABUTMENT
Path: P:\McKellar\2023\P1080125.jpg



Comments: SEVERE FLAKING OF STEEL GIRDER FLANGE
Path: P:\McKellar\2023\P1080117.jpg



Comments: SEVERE FLAKING OF STEEL GIRDER FLANGE
Path: P:\McKellar\2023\P1080122.jpg



Comments: LOSS OF ROCK FILL GABION BASKET RETAINING WALL

Path: P:\McKellar\2023\P1080123.jpg



Comments: LOSS OF ROCK FILL GABION BASKET RETAINING WALL

Path: P:\McKellar\2023\P1080119.jpg



Comments: WATERCOURSE UNDER BRIDGE
Path: P:\McKellar\2023\P1080114.jpg



Comments: LOOKING NORTH DOWNSTREAM
Path: P:\McKellar\2023\P1080115.jpg



Comments: LOOKING SOUTH UPSTREAM
Path: P:\McKellar\2023\P1080116.jpg

Comments:
Path:

MUNICIPAL BRIDGE APPRAISAL

A. IDENTIFICATION

Bridge Name: Hurdville Bridge	Bridge No.: 0004
Road Name: Hurdville Road	Road Section No.
Location: 6.80 km W of Centre Road	MTO Site No.: 044-0110-
Roadside Env.: R	Posting Sign: t t t
BL Posting: t t t	Low Clear Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 584374
Bylaw Exp. Date:	Northing: 5032529
	Crossing Type: O-WAT, Over Water
	Federal Navigable Waterway:
	Bridge Value: \$ 1,643,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage: 0.00	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Bridge No.:	MunicB
Shared With:		Patrol:
Heritage Status: D		

D. EXISTING CONDITIONS

Substructure Yr: 1930	Span Length: 6.1 m	Longitudinal Joints: 0
Superstructure Yr: 1930	Deck Type: CC - Concrete, Cast in Place	Transverse Joints: 1
Bridge Type: C - TB - H	Deck Length: 24.4 m	Number of Bearings: 0
Crossing Skew: -00 °	Deck Width: 5.0 m	Soil Condition: G
Number of Spans: 4	Deck Area: 122.0 m ²	Abutment and Foundation Type: Closed - SF

ROAD OVER BRIDGE

Existing Road Class: 200	No. of Lanes: 1.0	Barrier Walls/Railings: CB
Operational Status: 2W - OAT	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Wearing Surface: C	Safety Curb/ (A) N E 0.2 m	
Travel Deck Width: 4.00 m	Sidewalk and Curb (B) N / W 0.2 m	

ROAD UNDER BRIDGE

Existing Road Class:	No. of Lanes: 0	Traffic Barrier:
Operational Status: -	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Opening Under: m	Safety Curb/ (A) m	
Surface Width: m	Sidewalk and Curb (B) / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 100	AADT: 110
<input type="checkbox"/> School <input type="checkbox"/> Bike Route	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Bridge 0004 Asset Master	10 Year Growth Factor: 1.10	20 Year AADT: 121

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Bridge No.: 0004

MUNICIPAL BRIDGE APPRAISAL

G. BRIDGE NEEDS

Field	MCR	PCR	TON	Comments
Superstructure	4	5	1-5	
Wearing Surface	3	4	1-5	
Deck Condition	4	5	1-5	
Expansion Joints	0	0	ADEQ	
Railings	4	2	NOW	
Substructure	3	4	1-5	
Coating	0	0	ADEQ	
Streams/Waterways	5	5	6-10	
Curb/Sidewalk	5	5	6-10	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Bridge				
RO-Trav. Deck Width	4	6.5	NOW	
RO-LOS	A	E	ADEQ	
RO-Min. Vertical Clear.		4.5	ADEQ	No value for: Min Vertical Clearance
RO-Sidewalks	N	N	ADEQ	

Inspection

Impr.Class	Improvement	Description	Time of Need	Year	Base/ Const Cost	Eng/Cont	Total
Inspection	DCS	Deck Condition Survey	1-5	0	15,000	0	15,000
Inspection Subtotal:					15,000	0	15,000

Recommended Needs

Impr.Class	Improvement	Description	Time of Need	Year	Base/ Const Cost	Eng/Cont	Total
Rehab	CDS	Concrete Deck Soffit Repairs	1-5	0	15,000	5,000	20,000
Rehab	EIR	Embankment Improvement/Rehab	1-5	0	50,000	18,000	68,000
Rehab	RCS	Rehabilitation/Replacement of safety curbs	1-5	0	10,000	4,000	14,000
Rehab	RSB	Rehabilitate Substructure	1-5	0	90,000	32,000	122,000
Rehab	RSP	Rehabilitate Superstructure	1-5	0	20,000	7,000	27,000
Rehab	WSR	Wearing Surface Rehabilitation	1-5	0	10,000	4,000	14,000
Rehab	IAG	Install Approach Guiderail	NOW	0	70,000	25,000	95,000
Rehab	RIR	Railing Improvement/Replacement	NOW	0	40,000	14,000	54,000
Rehab Subtotal:					305,000	109,000	414,000
Rehab Extra	UNW	Unwatering	1-5	0	40,000	14,000	54,000
Rehab Extra	brAPP	Approaches	1-5	0	50,000	18,000	68,000
Rehab Extra	brENV	Environmental Study Costs	1-5	0	20,000	0	20,000
Rehab Extra	brMB	Mobilization / Bonds	1-5	0	8,000	3,000	11,000
Rehab Extra	brTCP	Traffic Control/Protection	1-5	0	10,000	4,000	14,000
Rehab Extra	brWPTF	Work Platforms	1-5	0	30,000	11,000	41,000
Rehab Extra	brMB	Mobilization / Bonds / Permits	NOW	0	5,000	2,000	7,000
Rehab Extra	brTCP	Traffic Control/Protection	NOW	0	10,000	4,000	14,000
Rehab Extra Subtotal:					173,000	56,000	229,000

MUNICIPAL BRIDGE APPRAISAL

I. ENGINEERING RECOMMENDATIONS

Bridge Drawings:
Estimated Posting: t
Evaluated Posting: t t t
Closure Date:
Closure Type:
Monitoring Interval:
Monitoring Component:

J. DESIGN PARAMETERS

Design Class:
Operational Status: -
Abutment Type:
Design Deck Width:
Design Deck Length:

K. IMPROVEMENT COSTS

Total Construction/Rehab	643,000
Total Inspection	15,000
TOTAL	658,000
86613 share @100%	658,000

INSPECTION NOTES

Bridge No.: 0004

Bridge No. 0004, Hurdville Bridge, Hurdville Road, Lot 35, Concession IV, 6.8 km West of Centre Road, Township of McKellar:

- Structure is not posted with a load limit.
- Four span (6.05 m+/-, 6.05 m+/-, 3.2 m+/-, 5.97 m+/-) concrete T-beam bridge with a concrete deck and exposed concrete wearing surface.
- A control dam structure is located immediately adjacent to the East side of the structure.
- Concrete wearing surface is in fair condition with narrow to wide cracks, light to severe scaling, asphalt patches and light delamination at the west end (5.0m², poor).
- Concrete expansion joint (transverse) is in fair condition with light to medium scaling.
- Concrete balustrade barrier wall is in fair to generally poor condition with narrow to wide cracking, concrete patches, overall light scaling and light abrasions, severe scaling and a severe spalling. There are nine missing balustrades on the east side that have been covered with an 8 ft length of steel flex beam. There are three loose balustrades on the west side (12.0m², poor)
- Concrete curbs are in generally good condition with overall light scaling, surface rust stains, narrow to wide cracking, light to severe delaminations and concrete patches (3.0m², poor). Curb upstand was measured to be 150 mm.
- Deck drainage is accommodated by 12 - 50 mm deck drains. Deck drains have been extended below the deck soffit with PVC piping. There are four missing deck drains (4, poor).
- Concrete deck soffit is in fair to generally good condition with light to severe delaminations and spalls, exposed corroded rebar, narrow to medium cracks with efflorescence, light scaling, wet areas and surface rust stains (5.0 m² - poor).
- Concrete T-beams are in generally good condition with localized light to severe delaminations and spalls, light scaling, narrow to medium cracks, wet areas and rust staining (1.0m², poor).
- Concrete abutments are in fair condition with narrow to wide horizontal cracks, light to severe delaminations and spalls, light to severe scaling, efflorescence, water staining, light to medium erosion, severe erosion adjacent to the dam structure allowing infiltration of water, and loss of bearing surface exterior girder south abutment (6.0 m² - poor). The deck has separated from abutment at the north end.
- Concrete piers are in poor to fair condition with overall light to severe scaling, efflorescence, encrustation, narrow to wide horizontal cracks, water staining, very severe erosion at the waterline and localized light to severe delaminations and severe spalls adjacent to the dam structure allowing the infiltration of water. (22.0 m² - poor)
- Concrete wingwalls are in fair condition with narrow to wide cracks, light to medium scaling, localized spalling and delaminations, light to severe erosion & efflorescence (2.0 m², poor).
- Surface treated approach roads are in generally good condition with narrow to wide cracks, asphalt patches, localized minor pothole adjacent to structure and minor settlement (1.0m², poor).
- Steel beam guide rail has been provided on the approaches with terminal end treatments. The approach guide rail is not connected to the barrier walls. Guide rail exhibits localized collision damage and outward rotation in the southeast and southwest quadrants. Intermediate guide rail posts have not been provided. Timber posts exhibit light to medium top rot and light to severe checks and splits.
- Hazard markers are provided in all four quadrants. All hazard markers are leaning.
- Roadway embankments are in fair to generally good condition with minor erosion in all quadrants. Severe erosion at the end of the approach guide rail at the Southwest.
- Watercourse is obstructed on the upstream side by a control dam.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.
- Should repair concrete deck, handrails, curbs, deck soffit, T-beams, piers, abutments, wingwalls, replace deck drain, surface approaches, restore embankments and replace approach guide rail. Should consider replacing barrier system (included in costing).
- Requires a detailed deck condition survey.
- Not costed for replacement for travel deck width deficiency due to low traffic volume.

L. HISTORY/ GENERAL

Bridge No.: 0004



Comments: LOOKING NORTH AT BRIDGE
Path: P:\McKellar\2023\P1080263.jpg



Comments: LOOKING SOUTH AT BRIDGE
Path: P:\McKellar\2023\P1080264.jpg



Comments: WEST ELEVATION

Path: P:\McKellar\2023\P1080265.jpg



Comments: EAST ELEVATION

Path: P:\McKellar\2023\P1080266.jpg



Comments: COLLISION DAMAGE TO NORTHEAST GUIDE RAIL

Path: P:\McKellar\2023\P1080267.jpg



Comments: BROKEN OFFSET BLOCK

Path: P:\McKellar\2023\P1080268.jpg



Comments: OUTWARD ROTATION OF APPROACH GUIDE RAIL SOUTHEAST QUADRANT

Path: P:\McKellar\2023\P1080270.jpg



Comments: WIDE TRANSVERSE CRACK APPROACH

Path: P:\McKellar\2023\P1080272.jpg



Comments: TYPICAL WEARING SURFACE

Path: P:\McKellar\2023\P1080274.jpg



Comments: WIDE CRACKS IN CONCRETE DECK

Path: P:\McKellar\2023\P1080275.jpg



Comments: GAP AT MIDSPAN OF DECK

Path: P:\McKellar\2023\P1080276.jpg



Comments: SEVERE SCALING OF CONCRETE DECK

Path: P:\McKellar\2023\P1080277.jpg



Comments: DELAMINATION NORTH END OF CONCRETE DECK

Path: P:\McKellar\2023\P1080278.jpg



Comments: WIDE CRACK IN CONCRETE CURB

Path: P:\McKellar\2023\P1080280.jpg



Comments: DELAMINATION IN CONCRETE CURB

Path: P:\McKellar\2023\P1080281.jpg



Comments: MISSING BALUSTRADE WEST RAILING

Path: P:\McKellar\2023\P1080269.jpg



Comments: MISSING BALUSTRADES ON EAST RAILING

Path: P:\McKellar\2023\P1080271.jpg



Comments: WIDE CRACKS IN BALUSTRADE

Path: P:\McKellar\2023\P1080273.jpg



Comments: SPALLING OF BALUSTRADE RAILING
Path: P:\McKellar\2023\P1080295.jpg



Comments: WIDE CRACK IN NORTHWEST WINGWALL
Path: P:\McKellar\2023\P1080283.jpg



Comments: WIDE VERTICAL CRACK IN WINGWALL

Path: P:\McKellar\2023\P1080302.jpg



Comments: WIDE CRACK IN EXTERIOR FASCIA

Path: P:\McKellar\2023\P1080290.jpg



Comments: TYPICAL NORTH ABUTMENT
Path: P:\McKellar\2023\P1080284.jpg



Comments: SEPARATION OF DECK AT NORTH ABUTMENT
Path: P:\McKellar\2023\P1080306.jpg



Comments: TYPICAL SOUTH ABUTMENT

Path: P:\McKellar\2023\P1080297.jpg



Comments: SEVERE SCOURING OF SOUTH ABUTMENT

Path: P:\McKellar\2023\P1080299.jpg



Comments: SEVERE DELAMINATIONS SOUTH ABUTMENT
Path: P:\McKellar\2023\P1080300.jpg



Comments: LOSS OF BEARING SURFACE BELOW EXTERIOR GIRDER SOUTH ABUTMENT
Path: P:\McKellar\2023\P1080301.jpg



Comments: TYPICAL PIER

Path: P:\McKellar\2023\P1080282.jpg



Comments: SEVERE DELAMINATIONS PIER

Path: P:\McKellar\2023\P1080291.jpg



Comments: SEVERE SCOURING OF PIER
Path: P:\McKellar\2023\P1080292.jpg



Comments: SEVERE SCOURING OF PIER AT WATERLINE
Path: P:\McKellar\2023\P1080303.jpg



Comments: WIDE HORIZONTAL CRACK IN PIER

Path: P:\McKellar\2023\P1080304.jpg



Comments: DELAMINATION INTERIOR SOFFIT

Path: P:\McKellar\2023\P1080288.jpg



Comments: SPALLING INTERIOR SOFFIT
Path: P:\McKellar\2023\P1080289.jpg



Comments: SEVERE DELAMINATIONS INTERIOR SOFFIT
Path: P:\McKellar\2023\P1080296.jpg



Comments: SEVERE DELAMINATIONS INTERIOR SOFFIT
Path: P:\McKellar\2023\P1080298.jpg



Comments: MISSING DECK DRAIN
Path: P:\McKellar\2023\P1080305.jpg



Comments: SEVERE EROSION OF ROADWAY EMBANKMENT SOUTHWEST QUADRANT

Path: P:\McKellar\2023\P1080308.jpg



Comments: WATERCOURSE UNDER BRIDGE

Path: P:\McKellar\2023\P1080293.jpg



Comments: LOOKING WEST DOWNSTREAM
Path: P:\McKellar\2023\P1080294.jpg



Comments: LOOKING EAST UPSTREAM
Path: P:\McKellar\2023\P1080307.jpg

MUNICIPAL BRIDGE APPRAISAL

A. IDENTIFICATION

Bridge Name: Stewart Park Bridge	Bridge No.: 0005
Road Name: Centre Road	Road Section No.
Location: 9.80 km S of Highway 124	MTO Site No.: 044-0111-
Roadside Env.: R	Posting Sign: t t t
BL Posting: t t t	Low Clear Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 589335
Bylaw Exp. Date:	Northing: 5034729
	Crossing Type: O-WAT, Over Water
	Federal Navigable Waterway:
	Bridge Value: \$ 2,343,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage: 0.00	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Bridge No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Substructure Yr: 1992	Span Length: 20.0 m	Longitudinal Joints: 0
Superstructure Yr: 1992	Deck Type: CC - Concrete, Cast in Place	Transverse Joints: 2
Bridge Type: P - IB - S	Deck Length: 21.0 m	Number of Bearings: 8
Crossing Skew: -00 °	Deck Width: 9.4 m	Soil Condition: F
Number of Spans: 1	Deck Area: 197.4 m ²	Abutment and Foundation Type: Open - SF

ROAD OVER BRIDGE

Existing Road Class: 200	No. of Lanes: 2.0	Barrier Walls/Railings: NJ
Operational Status: 2W - OAT	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Wearing Surface: A	Safety Curb/ (A) N E 0.0 m	
Travel Deck Width: 6.50 m	Sidewalk and Curb (B) N / W 0.0 m	

ROAD UNDER BRIDGE

Existing Road Class:	No. of Lanes: 0	Traffic Barrier:
Operational Status: -	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Opening Under: m	Safety Curb/ (A) m	
Surface Width: m	Sidewalk and Curb (B) / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 80	AADT: 88
<input checked="" type="checkbox"/> School <input type="checkbox"/> Bike Route	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Bridge 0005 Asset Master	10 Year Growth Factor: 1.10	20 Year AADT: 96

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Bridge No.: 0005

MUNICIPAL BRIDGE APPRAISAL

G. BRIDGE NEEDS

Field	MCR	PCR	TON	Comments
Superstructure	5	5	6-10	
Wearing Surface	5	5	6-10	
Deck Condition	5	5	6-10	
Expansion Joints	5	5	6-10	
Railings	4	5	1-5	
Substructure	5	5	6-10	
Coating	0	0	ADEQ	
Streams/Waterways	4	5	1-5	
Curb/Sidewalk	0	0	ADEQ	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Bridge				
RO-Trav. Deck Width	6.5	6.5	ADEQ	Proj Class: 200, 88 (10 YR, 80*1.1)
RO-LOS	A	E	ADEQ	
RO-Min. Vertical Clear.		4.5	ADEQ	No value for: Min Vertical Clearance
RO-Sidewalks	N	N	ADEQ	

Recommended Needs

Impr.Class	Improvement	Description	Time of Need	Year	Base/ Const Cost	Eng/Cont	Total
Maintenance	OTH	Maintenance Improvement	NOW	0	0	0	0
			Maintenance Subtotal:		0	0	0
Rehab	EIR	Embankment Improvement/Rehab	1-5	0	10,000	4,000	14,000
			Rehab Subtotal:		10,000	4,000	14,000
Rehab Extra	brAPP	Approaches	1-5	0	5,000	2,000	7,000
Rehab Extra	brMB	Mobilization / Bonds	1-5	0	1,000	0	1,000
Rehab Extra	brTCP	Traffic Control/Protection	1-5	0	5,000	2,000	7,000
			Rehab Extra Subtotal:		11,000	4,000	15,000

I. ENGINEERING RECOMMENDATIONS

Bridge Drawings:
 Estimated Posting: t
 Evaluated Posting: t t t
 Closure Date:
 Closure Type:
 Monitoring Interval:
 Monitoring Component:

J. DESIGN PARAMETERS

Design Class:
 Operational Status: -
 Abutment Type:
 Design Deck Width:
 Design Deck Length:

K. IMPROVEMENT COSTS

Total Construction/Rehab	29,000
Total Inspection	0
TOTAL	29,000
86613 share @100%	29,000

INSPECTION NOTES

Bridge No.: 0005

Bridge No. 0005, Stewart Park Bridge, Centre Road, Lot 22, Concession IV/V, 9.8 km South of Highway 124, Township of McKellar:

- Structure is not posted with a load limit.
- 20.0 m+- single span precast concrete girder bridge with a concrete deck and asphalt wearing surface.
- Asphalt wearing surface is in generally good condition with narrow cracks and water ponding on the deck.
- Concrete barrier walls are in generally good condition with localized map cracking, narrow stained and unstained cracks and light abrasions.
- Steel barrier handrails are provided on top of the concrete barrier walls and are in fair to good condition with minor to moderate collision damage of nine (9) anchor brackets, cracking, light corrosion and 7 missing bolts. The east railing is loose and the posts are leaning. End caps are missing in northeast and southwest quadrants (6.0m, poor).
- Deck drainage is accommodated by 6 - 200 mm diameter galvanized deck drains that outlet flush with the bottom of the girders.
- Armoured expansion joints are in generally good condition with light corrosion, minor scrape damage and filled with debris.
- Concrete end dams are in generally good condition with narrow transverse cracks, light scaling and surface rust staining. The end dams have been paved over.
- Concrete deck soffit is in generally good condition with light to medium honeycombing in the Northwest quadrant and localized hairline stained crack in Southeast quadrant.
- Concrete diaphragms are in good condition.
- Elastomeric abutment bearing pads are in good condition.
- Precast concrete girders are in good condition with bird nests.
- Concrete abutments and ballast walls are in generally good condition with water staining, rust staining, narrow to medium vertical stained and unstained cracks, light erosion at the waterline and localized light abrasion.
- Concrete wingwalls are in generally good condition with narrow stained and unstained cracks.
- Asphalt paved approach roads are in generally good condition with narrow cracks at ends.
- Concrete curbs are in generally good condition with light scaling.
- Roadway embankments are in generally good condition with minor erosion at the Northeast quadrant, moderate erosion at the Northwest quadrant. Severe erosion with undermining at Southwest. Rip rap slope protection in front of the abutments and wingwalls is in good condition.
- Steel beam guide rail is provided in all four quadrants of the structure and is in good condition. Eccentric loader end treatments have been provided in all quadrants. Timber posts exhibit light to medium splits and checks with localized top rot.
- Watercourse is unobstructed with no evidence of scour.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.
- Should install a form and fill groove at the ends of the approach slabs and restore embankments.
- Should replace missing barrier rail end cap, replace broken/bent handrail post and reposition guide rail posts as part of regular structure maintenance.

L. HISTORY/ GENERAL

Bridge No.: 0005



Comments: LOOKING NORTH AT BRIDGE
Path: P:\McKellar\2023\P1080234.jpg



Comments: LOOKING SOUTH AT BRIDGE
Path: P:\McKellar\2023\P1080235.jpg



Comments: EAST ELEVATION

Path: P:\McKellar\2023\P1080236.jpg



Comments: WEST ELEVATION

Path: P:\McKellar\2023\P1080237.jpg



Comments: COLLISION DAMAGE APPROACH GUIDE RAIL

Path: P:\McKellar\2023\P1080238.jpg



Comments: CENTRE ROT OF TIMBER GUIDE RAIL POST

Path: P:\McKellar\2023\P1080239.jpg



Comments: MEDIUM CHECK IN TIMBER GUIDE RAIL POST

Path: P:\McKellar\2023\P1080262.jpg



Comments: TYPICAL WEARING SURFACE

Path: P:\McKellar\2023\P1080243.jpg



Comments: NARROW CRACKS IN DECK WEARING SURFACE

Path: P:\McKellar\2023\P1080245.jpg



Comments: LIGHT CORROSION OF ARMOURING ANGLE

Path: P:\McKellar\2023\P1080244.jpg



Comments: NARROW STAINED CRACKS INTERIOR PARAPET WALL

Path: P:\McKellar\2023\P1080240.jpg



Comments: LIGHT ABRASION INTERIOR PARAPET WALL

Path: P:\McKellar\2023\P1080246.jpg



Comments: LIGHT ABRASION PARAPET END POST

Path: P:\McKellar\2023\P1080247.jpg



Comments: MISSING END CAP SOUTHWEST QUADRANT

Path: P:\McKellar\2023\P1080241.jpg



Comments: COLLISION DAMAGE TO HANDRAIL POST
Path: P:\McKellar\2023\P1080242.jpg



Comments: NARROW STAINED CRACK EXTERIOR PARAPET WALL
Path: P:\McKellar\2023\P1080251.jpg



Comments: NARROW STAINED CRACK IN WINGWALL

Path: P:\McKellar\2023\P1080254.jpg



Comments: TYPICAL SOUTH ABUTMENT

Path: P:\McKellar\2023\P1080248.jpg



Comments: TYPICAL ABUTMENT BEARING

Path: P:\McKellar\2023\P1080250.jpg



Comments: MEDIUM VERTICAL CRACK SOUTH ABUTMENT

Path: P:\McKellar\2023\P1080261.jpg



Comments: LIGHT EROSION OF SOUTH ABUTMENT AT WATERLINE
Path: P:\McKellar\2023\P1080258.jpg



Comments: TYPICAL NORTH ABUTMENT
Path: P:\McKellar\2023\P1080257.jpg



Comments: TYPICAL SOFFIT

Path: P:\McKellar\2023\P1080259.jpg



Comments: MEDIUM HONEYCOMBING EXTERIOR GIRDER

Path: P:\McKellar\2023\P1080255.jpg



Comments: WATERCOURSE UNDER BRIDGE
Path: P:\McKellar\2023\P1080252.jpg



Comments: LOOKING EAST UPSTREAM
Path: P:\McKellar\2023\P1080253.jpg



Comments: LOOKING WEST DOWNSTREAM

Path: P:\McKellar\2023\P1080260.jpg



Comments: EROSION IN SOUTHWEST QUADRANT

Path: P:\McKellar\2023\P1080256.jpg

MUNICIPAL BRIDGE APPRAISAL

A. IDENTIFICATION

Bridge Name: Broadbent Bridge	Bridge No.: 0006
Road Name: Dickinson Road	Road Section No.
Location: 0.20 km W of Broadbent Road	MTO Site No.: 044-0112-
Roadside Env.: R	Posting Sign: t t t
BL Posting: t t t	Low Clear Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 591513
Bylaw Exp. Date:	Northing: 5035361
	Crossing Type: O-WAT, Over Water
	Federal Navigable Waterway:
	Bridge Value: \$ 1,290,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage: 0.00	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Bridge No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Substructure Yr: 1910	Span Length: 16.3 m	Longitudinal Joints: 0
Superstructure Yr: 2008	Deck Type: SP - Steel Plate, Non-composit	Transverse Joints: 0
Bridge Type: W - IB - S	Deck Length: 17.3 m	Number of Bearings: 4
Crossing Skew: -00 °	Deck Width: 4.1 m	Soil Condition: G
Number of Spans: 1	Deck Area: 71.0 m ²	Abutment and Foundation Type: Open - SF

ROAD OVER BRIDGE

Existing Road Class: 100	No. of Lanes: 1.0	Barrier Walls/Railings: OT
Operational Status: 2W - OAT	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Wearing Surface: A	Safety Curb/ (A) N N 0.0 m	
Travel Deck Width: 4.00 m	Sidewalk and Curb (B) N / S 0.0 m	

ROAD UNDER BRIDGE

Existing Road Class:	No. of Lanes: 0	Traffic Barrier:
Operational Status: -	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Opening Under: m	Safety Curb/ (A) m	
Surface Width: m	Sidewalk and Curb (B) / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 10	AADT: 11
<input type="checkbox"/> School <input type="checkbox"/> Bike Route	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Bridge 0006 Asset Master	10 Year Growth Factor: 1.10	20 Year AADT: 12

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Bridge No.: 0006

MUNICIPAL BRIDGE APPRAISAL

G. BRIDGE NEEDS

Field	MCR	PCR	TON	Comments
Superstructure	3	4	1-5	
Wearing Surface	5	5	6-10	
Deck Condition	5	5	6-10	
Expansion Joints	0	0	ADEQ	
Railings	5	5	6-10	
Substructure	5	6	6-10	
Coating	0	0	ADEQ	
Streams/Waterways	5	6	6-10	
Curb/Sidewalk	0	0	ADEQ	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Bridge				
RO-Trav. Deck Width	4	6.5	NOW	
RO-LOS	A	E	ADEQ	
RO-Min. Vertical Clear.		4.5	ADEQ	No value for: Min Vertical Clearance
RO-Sidewalks	N	N	ADEQ	

Recommended Needs

Impr.Class	Improvement	Description	Time of Need	Year	Base/Const Cost	Eng/Cont	Total
Maintenance	OTH	Maintenance Improvement	NOW	0	0	0	0
Maintenance Subtotal:					0	0	0
Rehab	CSS	Coating Structural Steel	1-5	0	60,000	21,000	81,000
Rehab	RSP	Rehabilitate Superstructure	1-5	0	6,000	2,000	8,000
Rehab Subtotal:					66,000	23,000	89,000
Rehab Extra	brDET	Detours	1-5	0	10,000	4,000	14,000
Rehab Extra	brENV	Environmental Study Costs	1-5	0	20,000	0	20,000
Rehab Extra	brMB	Mobilization / Bonds / Permits	1-5	0	5,000	2,000	7,000
Rehab Extra	brWPTF	Work Platforms / Access	1-5	0	30,000	11,000	41,000
Rehab Extra Subtotal:					65,000	17,000	82,000

I. ENGINEERING RECOMMENDATIONS

Bridge Drawings:

Estimated Posting: t

Evaluated Posting: t t t

Closure Date:

Closure Type:

Monitoring Interval:

Monitoring Component:

J. DESIGN PARAMETERS

Design Class:

Operational Status: -

Abutment Type:

Design Deck Width:

Design Deck Length:

K. IMPROVEMENT COSTS

Total Construction/Rehab	171,000
Total Inspection	0
TOTAL	171,000
86613 share @100%	171,000

INSPECTION NOTES

Bridge No.: 0006

Bridge No. 0006, Broadbent Bridge, Dickinson Road, Lot 16, Conc IV, 0.20 km West of Broadbent Road, Township of McKellar:

- Structure is not posted with a load limit.
- 16.3m +/- single span weathering steel girder bridge with steel deck.
- Thrie beam guide rail is in generally good condition with minor collision damage and light corrosion.
- Steel plate deck is in generally good condition, light to medium corrosion and localized severe corrosion at ends.
- Asphalt wearing surface is in good condition.
- Steel girders and stringers are in generally good condition with light to medium flaking of patina and rust jacking of stringer at the north abutment. Three stringers at the north abutment exhibit severe perforations and section loss. (1.0m², poor)
- Steel diaphragms are in generally good condition with light flaking of patina, medium flaking of patina at ends.
- Elasmometric bearings are in generally good condition and are covered in debris. One bearing pad at the north abutment is displaced.
- Concrete ballast walls are in generally good condition with light scaling, exposed rebar at the south end and a wide vertical crack at the north end.
- Stone masonry abutments are in generally good condition with efflorescence staining, wet areas and a broken section in the northwest quadrant (1.0m², poor).
- Stone masonry wingwalls are in generally good condition with efflorescent stained cracks.
- Watercourse is unobstructed with no evidence of scour.
- Asphalt paved approach roads are in good condition.
- Roadway embankments are in generally good condition with minor erosion at Northwest.
- Steel beam guide rails are provided on the approaches and are in generally good condition with four posts not attached to the guide rail. Extruder end treatments have been provided in all four quadrants. Both end treatments are the North exhibit light to medium collision damage. The northwest end treatment is missing hazard marker cover.
- No serious evidence of structural distress.
- Not costed for replacement for travel deck width deficiency due to low traffic volume.
- Should repair guide rail end treatments as part of structure maintenance.
- Should clean and paint structural steel at the abutments and repair deteriorated stringers at abutments

L. HISTORY/ GENERAL

Bridge No.: 0006

Year: 2008, , Est Cost: 0

Work Summary: 2008 Superstructure replacement

Year: 2022, WSR Wearing Surface Rehabilitation, Est Cost: 0



Comments: LOOKING NORTH AT BRIDGE
Path: P:\McKellar\2023\P1080206.jpg



Comments: LOOKING SOUTH AT BRIDGE
Path: P:\McKellar\2023\P1080207.jpg



Comments: EAST ELEVATION

Path: P:\McKellar\2023\P1080214.jpg



Comments: WEST ELEVATION

Path: P:\McKellar\2023\P1080221.jpg



Comments: MISSING END TREATMENT HAZARD MARKER NW QUADRANT
Path: P:\McKellar\2023\P1080208.jpg



Comments: COLLISION DAMAGE NORTHEAST END TREATMENT POST
Path: P:\McKellar\2023\P1080209.jpg



Comments: GUIDE RAIL DISCONNECTED GUIDE RAIL NORTH APPROACH

Path: P:\McKellar\2023\P1080210.jpg



Comments: TYPICAL WEARING SURFACE

Path: P:\McKellar\2023\P1080211.jpg



Comments: MINOR COLLISION DAMAGE THRIE BEAM GUIDE RAIL
Path: P:\McKellar\2023\P1080233.jpg



Comments: COLLISION DAMAGE GUIDE RAIL C-CHANNEL
Path: P:\McKellar\2023\P1080212.jpg



Comments: BROKEN SECTION OF NORTHWEST WINGWALL

Path: P:\McKellar\2023\P1080227.jpg



Comments: EFFLORESCENT STAINING NORTHWEST WINGWALL

Path: P:\McKellar\2023\P1080228.jpg



Comments: TYPICAL NORTH ABUTMENT
Path: P:\McKellar\2023\P1080215.jpg



Comments: WIDE VERTICAL CRACK NORTH BALLAST WALL
Path: P:\McKellar\2023\P1080230.jpg



Comments: TYPICAL SOUTH ABUTMENT
Path: P:\McKellar\2023\P1080216.jpg



Comments: EFFLORESCENT STAINING SOUTH ABUTMENT
Path: P:\McKellar\2023\P1080222.jpg



Comments: EFFLORESCENT STAINING SOUTH ABUTMENT CAP
Path: P:\McKellar\2023\P1080223.jpg



Comments: DISPLACED ELASTOMERIC BEARING PAD NORTH ABUTMENT
Path: P:\McKellar\2023\P1080231.jpg



Comments: TYPICAL SOFFIT

Path: P:\McKellar\2023\P1080217.jpg



Comments: LIGHT FLAKING OF PATINA GIRDER

Path: P:\McKellar\2023\P1080226.jpg



Comments: MEDIUM FLAKING OF STEEL GIRDER BOTTOM FLANGE
Path: P:\McKellar\2023\P1080232.jpg



Comments: SEVERE CORROSION WITH SECTION LOSS FLOOR BEAM NORTH ABUTMENT
Path: P:\McKellar\2023\P1080229.jpg



Comments: WATERCOURSE UNDER BRIDGE
Path: P:\McKellar\2023\P1080218.jpg



Comments: LOOKING EAST UPSTREAM
Path: P:\McKellar\2023\P1080219.jpg



Comments: LOOKING WEST DOWNSTREAM
Path: P:\McKellar\2023\P1080220.jpg

Comments:
Path:

MUNICIPAL BRIDGE APPRAISAL

A. IDENTIFICATION

Bridge Name: Inholmes Bridge	Bridge No.: 0007
Road Name: Broadbent Road	Road Section No.
Location: 7.20 km N of Hurdville Road	MTO Site No.: 044-0113-
Roadside Env.: R	Posting Sign: t t t
BL Posting: t t t	Low Clear Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 594092
Bylaw Exp. Date: 2/01/2010	Northing: 5038592
	Crossing Type: O-WAT, Over Water
	Federal Navigable Waterway:
	Bridge Value: \$ 1,590,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage: 0.00	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Bridge No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Substructure Yr: 1920	Span Length: 9.3 m	Longitudinal Joints: 0
Superstructure Yr: 2023	Deck Type: CC - Concrete, Cast in Place	Transverse Joints: 0
Bridge Type: S - IB - S	Deck Length: 19.6 m	Number of Bearings: 16
Crossing Skew: -00 °	Deck Width: 4.9 m	Soil Condition: G
Number of Spans: 2	Deck Area: 96.4 m ²	Abutment and Foundation Type: Closed - SF

ROAD OVER BRIDGE

Existing Road Class: 200	No. of Lanes: 1.0	Barrier Walls/Railings: FB
Operational Status: 2W - OAT	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Wearing Surface: A	Safety Curb/ (A) N E 0.0 m	
Travel Deck Width: 4.80 m	Sidewalk and Curb (B) N / W 0.0 m	

ROAD UNDER BRIDGE

Existing Road Class:	No. of Lanes: 0	Traffic Barrier:
Operational Status: -	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Opening Under: m	Safety Curb/ (A) m	
Surface Width: m	Sidewalk and Curb (B) / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 50	AADT: 55
<input type="checkbox"/> School <input type="checkbox"/> Bike Route	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Bridge 0007 Asset Master	10 Year Growth Factor: 1.10	20 Year AADT: 60

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Bridge No.: 0007

MUNICIPAL BRIDGE APPRAISAL

G. BRIDGE NEEDS

Field	MCR	PCR	TON	Comments
Superstructure	6	6	ADEQ	
Wearing Surface	6	6	ADEQ	
Deck Condition	6	6	ADEQ	
Expansion Joints	0	0	ADEQ	
Railings	6	6	ADEQ	
Substructure	5	5	6-10	
Coating	6	6	ADEQ	
Streams/Waterways	5	5	6-10	
Curb/Sidewalk	0	0	ADEQ	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Bridge				
RO-Trav. Deck Width	4.8	6.5	NOW	
RO-LOS	A	E	ADEQ	
RO-Min. Vertical Clear.		4.5	ADEQ	No value for: Min Vertical Clearance
RO-Sidewalks	N	N	ADEQ	

Recommended Needs

Impr.Class	Improvement Description	Time of Need	Year	Base/Const Cost	Eng/Cont	Total
------------	-------------------------	--------------	------	-----------------	----------	-------

There are no needs identified in this inspection.

I. ENGINEERING RECOMMENDATIONS

Bridge Drawings:			
Estimated Posting:	t		
Evaluated Posting:	t	t	t
Closure Date:			
Closure Type:			
Monitoring Interval:			
Monitoring Component:			

J. DESIGN PARAMETERS

Design Class:	
Operational Status:	-
Abutment Type:	
Design Deck Width:	
Design Deck Length:	

K. IMPROVEMENT COSTS

Total Construction/Rehab	0
Total Inspection	0
TOTAL	0
86613 share @100%	0

INSPECTION NOTES

Bridge No.: 0007

Bridge No. 0007, Inholmes Bridge, Broadbent Road, Lot 7, Concession VI, 7.20 km North of Hurdville Road, Township of McKellar:

- Structure is not posted with a load limit.
- Two span (9.5 m+/- each) structural steel girder bridge with a concrete deck and asphalt wearing surface.
- Steel flex beam guide rail over the structure is in excellent condition.
- Asphalt wearing surface is in excellent condition.
- Steel stay in place deck soffit is in excellent condition.
- Structural steel girders are in excellent condition.
- Structural steel floor beams are in excellent condition.
- Structural steel diaphragms are in excellent condition.
- Stone masonry abutments are in generally good condition with new concrete bearing surfaces and have been tuck pointed. The mortar is loose and missing in some areas. The South abutment wall has two missing stones. Abutment footings exhibit light to severe erosion (1.0m², poor).
- Stone masonry pier is in generally good condition with new concrete bearing surface. Stone masonry pier has been tuck pointed but has some loose and missing mortar joints.
- Steel pier nosing is in generally good condition with overall surface corrosion, light pitting.
- Structural steel bearings at the abutments and pier are in excellent condition.
- Stone masonry wingwalls are in generally good condition with vertical cracks and localized loss of mortar. Southwest wingwall has a wide vertical crack and is showing signs of outward rotation at the Southwest.
- Asphalt approach roads are in excellent condition.
- Steel beam guide rail has been provided on the approaches as is in good condition. Eccentric loader end treatments have been provided in each quadrant.
- Hazard markers are located in all four quadrants of the structure.
- Roadway embankments are in good condition, rock protection has been provided in the southwest quadrant.
- Watercourse is unobstructed with no evidence of scour.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.

L. HISTORY/ GENERAL

Bridge No.: 0007

Year: 2023, RSP Rehabilitate Superstructure, Est Cost: 0

Year: 2023, RSB Rehabilitate Substructure, Est Cost: 0



Comments: LOOKING SOUTH AT BRIDGE

Path: P:\McKellar\2023\P1080184.jpg



Comments: LOOKING NORTH AT BRIDGE

Path: P:\McKellar\2023\P1080185.jpg



Comments: WEST ELEVATION

Path: P:\McKellar\2023\P1080191.jpg



Comments: EAST ELEVATION

Path: P:\McKellar\2023\P1080202.jpg



Comments: TYPICAL WEARING SURFACE
Path: P:\McKellar\2023\P1080188.jpg



Comments: MINOR DETERIORATION OF ASPHALT AT DECK END
Path: P:\McKellar\2023\P1080188.jpg



Comments: NEW GUIDE RAIL INSTALLED OVER DECK

Path: P:\McKellar\2023\P1080187.jpg



Comments: TYPICAL SOUTH ABUTMENT

Path: P:\McKellar\2023\P1080199.jpg



Comments: TYPICAL NORTH ABUTMENT
Path: P:\McKellar\2023\P1080201.jpg



Comments: TYPICAL ABUTMENT BEARING
Path: P:\McKellar\2023\P1080198.jpg



Comments: TYPICAL PIER

Path: P:\McKellar\2023\P1080192.jpg



Comments: TYPICAL PIER

Path: P:\McKellar\2023\P1080200.jpg



Comments: TYPICAL PIER BEARINGS

Path: P:\McKellar\2023\P1080203.jpg



Comments: TYPICAL SOFFIT

Path: P:\McKellar\2023\P1080193.jpg



Comments: ROCK PROTECTION PROVIDED IN SOUTHWEST QUADRANT

Path: P:\McKellar\2023\P1080190.jpg



Comments: WATERCOURSE UNDER BRIDGE

Path: P:\McKellar\2023\P1080194.jpg



Comments: LOOKING WEST DOWNSTREAM
Path: P:\McKellar\2023\P1080195.jpg



Comments: LOOKING EAST UPSTREAM
Path: P:\McKellar\2023\P1080196.jpg

MUNICIPAL BRIDGE APPRAISAL

A. IDENTIFICATION

Bridge Name: Ford Bridge	Bridge No.: 0008
Road Name: Broadbent Road	Road Section No.
Location: 8.70 km N of Hurdville Road	MTO Site No.: 044-0114-
Roadside Env.: R	Posting Sign: t t t
BL Posting: t t t	Low Clear Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 595039
Bylaw Exp. Date:	Northing: 5039564
	Crossing Type: O-WAT, Over Water
	Federal Navigable Waterway:
	Bridge Value: \$ 1,215,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage: 0.00	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Bridge No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Substructure Yr: 1930	Span Length: 12.2 m	Longitudinal Joints: 0
Superstructure Yr: 1930	Deck Type: CC - Concrete, Cast in Place	Transverse Joints: 0
Bridge Type: C - TB - H	Deck Length: 13.1 m	Number of Bearings: 0
Crossing Skew: -00 °	Deck Width: 5.7 m	Soil Condition: G
Number of Spans: 1	Deck Area: 74.7 m ²	Abutment and Foundation Type: Closed - SF

ROAD OVER BRIDGE

Existing Road Class: 200	No. of Lanes: 1.0	Barrier Walls/Railings: CP
Operational Status: 2W - OAT	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Wearing Surface: A	Safety Curb/ (A) N 0.2 m	
Travel Deck Width: 4.70 m	Sidewalk and Curb (B) N / S 0.2 m	

ROAD UNDER BRIDGE

Existing Road Class:	No. of Lanes: 0	Traffic Barrier:
Operational Status: -	Median Type/Width: 0.0 m	Min Vertical Clearance: m
Opening Under: m	Safety Curb/ (A) m	
Surface Width: m	Sidewalk and Curb (B) / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 50	AADT: 55
<input type="checkbox"/> School <input type="checkbox"/> Bike Route	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Bridge 0008 Asset Master	10 Year Growth Factor: 1.10	20 Year AADT: 60

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Bridge No.: 0008

MUNICIPAL BRIDGE APPRAISAL

G. BRIDGE NEEDS

Field	MCR	PCR	TON	Comments
Superstructure	4	5	1-5	
Wearing Surface	4	5	1-5	
Deck Condition	4	5	1-5	
Expansion Joints	0	0	ADEQ	
Railings	4	5	1-5	
Substructure	4	5	1-5	
Coating	0	0	ADEQ	
Streams/Waterways	5	5	6-10	
Curb/Sidewalk	5	5	6-10	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Bridge				
RO-Trav. Deck Width	4.7	6.5	NOW	
RO-LOS	A	E	ADEQ	
RO-Min. Vertical Clear.		4.5	ADEQ	No value for: Min Vertical Clearance
RO-Sidewalks	N	N	ADEQ	

Recommended Needs

Impr.Class	Improvement	Description	Time of Need	Year	Base/ Const Cost	Eng/Cont	Total
Maintenance	OTH	Maintenance Improvement	NOW	0	0	0	0
Maintenance Subtotal:					0	0	0
Rehab	EIR	Embankment Improvement/Rehab	1-5	0	15,000	5,000	20,000
Rehab	RIR	Railing Improvement/Replacement	1-5	0	10,000	4,000	14,000
Rehab	RSB	Rehabilitate Substructure	1-5	0	10,000	4,000	14,000
Rehab	RSP	Rehabilitate Superstructure	1-5	0	15,000	5,000	20,000
Rehab Subtotal:					50,000	18,000	68,000
Rehab Extra	brMB	Mobilization / Bonds	1-5	0	4,000	2,000	6,000
Rehab Extra	brTCP	Traffic Control/Protection	1-5	0	10,000	4,000	14,000
Rehab Extra	brWPTF	Work Platforms	1-5	0	25,000	9,000	34,000
Rehab Extra Subtotal:					39,000	15,000	54,000

I. ENGINEERING RECOMMENDATIONS

Bridge Drawings:
 Estimated Posting: t
 Evaluated Posting: t t t
 Closure Date:
 Closure Type:
 Monitoring Interval:
 Monitoring Component:

J. DESIGN PARAMETERS

Design Class:
 Operational Status: -
 Abutment Type:
 Design Deck Width:
 Design Deck Length:

K. IMPROVEMENT COSTS

Total Construction/Rehab	122,000
Total Inspection	0
TOTAL	122,000
86613 share @100%	122,000

INSPECTION NOTES

Bridge No.: 0008

Bridge No. 0008, Ford Bridge, Broadbent Road, Lot 4, Concession VII, 8.70 km North of Hurdville Road, Township of McKellar:

- Structure is not posted with a load limit.
- 1.2 m+/- single span concrete T-beam bridge with a concrete deck and an asphalt wearing surface.
- Asphalt wearing surface is in generally good condition with light ravelling, narrow cracks and light flushing.
- Concrete barrier walls are in fair to generally good condition with narrow to medium cracks, patched cracks, localized wide cracks, surface rust stains, light to severe scaling, abrasions, concrete patches, debonded concrete patches, efflorescence and narrow stained cracks (2.0m², poor).
- Concrete curbs are in generally good condition with overall light to medium scaling and concrete patches. Curb upstand was measured to be 75 mm.
- Deck drainage is accommodated by 9 - 50 mm deck drains that outlet through the structure, two drains are covered with sand.
- Concrete deck fascias are in generally good condition with concrete patches, delaminations, overall light scaling and localized severe scaling of the South side (1.0m², poor).
- Concrete deck soffit is in generally good condition with light scaling, localized narrow stained cracks, localized wet areas and moderate scaling noted at the deck drain outlets (1.0m², poor).
- Concrete T-beams are in fair to generally good condition with surface rust staining, wet areas, light to severe scaling, efflorescence, light to severe spalling and delaminations, narrow to wide cracks, concrete patch (7.0m², poor).
- Concrete abutments are in generally good condition with light to severe erosion, light to medium scaling, water staining, efflorescence, concrete patches, localized wide cracks in the west abutment, timber work left in place, light spall (2.0m², poor). The top of the footings are exposed and are in generally fair condition with overall light to medium erosion.
- Concrete wingwalls are in fair to generally good condition with concrete patches, debonded concrete patches, narrow stained and unstained cracks, efflorescence, light to severe scaling, localized wide cracks and localized severe spall at Southwest (3.0m², poor).
- Asphalt paved approach roads are in generally fair condition with asphalt patches, minor to moderate settlement at both approaches, light to severe alligator cracking, narrow cracks (1.0m², poor).
- Steel beam guide rail is in generally good condition. Approach guide rail is not properly connected to the structure. Rail is not sitting on some of the angle clips. Eccentric loader end treatments are provided in all four quadrants and are in good condition. Hazard markers are provided in all four quadrants. Northwest hazard markers is leaning slightly.
- Roadway embankments are in generally poor to fair condition with moderate erosion in Southwest and Southeast, and severe erosion in Northeast and Northwest quadrants.
- Watercourse is unobstructed with no evidence of scour.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.
- Should repair parapet walls, T-beams, abutments, wingwalls and restore embankments.
- Should repair approaches, adjust guide rail, replace leaning hazard markers and unplug deck drains as part of regular structure maintenance.
- Not costed for replacement for travel deck width deficiency due to low traffic volume.

L. HISTORY/ GENERAL

Bridge No.: 0008

Year: 2009, IAG Install Approach Guiderail, Est Cost: 0



Comments: LOOKING EAST AT BRIDGE

Path: P:\McKellar\2023\P1080153.jpg



Comments: LOOKING WEST AT BRIDGE

Path: P:\McKellar\2023\P1080154.jpg



Comments: SOUTH ELEVATION

Path: P:\McKellar\2023\P1080155.jpg



Comments: NORTH ELEVATION

Path: P:\McKellar\2023\P1080156.jpg



Comments: MINOR COLLISION DAMAGE GUIDE RAIL
Path: P:\McKellar\2023\P1080157.jpg



Comments: SEVERE MAP CRACKING APPROACH WEARING SURFACE
Path: P:\McKellar\2023\P1080158.jpg



Comments: SETTLEMENT OF WEST APPROACH

Path: P:\McKellar\2023\P1080166.jpg



Comments: TYPICAL DECK WEARING SURFACE

Path: P:\McKellar\2023\P1080159.jpg



Comments: LIGHT FLUSHING OF DECK WEARING SURFACE

Path: P:\McKellar\2023\P1080160.jpg



Comments: SEVERE SPALL BARRIER WALL

Path: P:\McKellar\2023\P1080161.jpg



Comments: DEBONDED CONCRETE PATCH BARRIER WALL

Path: P:\McKellar\2023\P1080162.jpg



Comments: WIDE CRACK IN CONCRETE CURB

Path: P:\McKellar\2023\P1080164.jpg



Comments: MEDIUM SCALING ALONG CURB LINE

Path: P:\McKellar\2023\P1080165.jpg



Comments: SEVERE SCALING SOUTHWEST WINGWALL

Path: P:\McKellar\2023\P1080173.jpg



Comments: WIDE VERTICAL CRACK SOUTHWEST WINGWALL

Path: P:\McKellar\2023\P1080174.jpg



Comments: WIDE VERTICAL CRACK NORTHWEST WINGWALL

Path: P:\McKellar\2023\P1080178.jpg



Comments: TYPICAL EAST ABUTMENT

Path: P:\McKellar\2023\P1080167.jpg



Comments: TYPICAL WEST ABUTMENT

Path: P:\McKellar\2023\P1080168.jpg



Comments: TYPICAL SOFFIT

Path: P:\McKellar\2023\P1080169.jpg



Comments: WIDE VERTICAL CRACK WEST ABUTMENT

Path: P:\McKellar\2023\P1080176.jpg



Comments: SEVERE DELAMINATION EXTERIOR FASCIA

Path: P:\McKellar\2023\P1080181.jpg



Comments: SEVERE DELAMINATION T-BEAM GIRDER

Path: P:\McKellar\2023\P1080183.jpg



Comments: SPALLING OF T-BEAM GIRDER

Path: P:\McKellar\2023\P1080175.jpg



Comments: SEVERE DELAMINATION T-BEAM GIRDER

Path: P:\McKellar\2023\P1080177.jpg



Comments: SEVERE SPALLING OF T-BEAM GIRDER
Path: P:\McKellar\2023\P1080179.jpg



Comments: WATER STAINING INTERIOR SOFFIT
Path: P:\McKellar\2023\P1080180.jpg



Comments: SEVERE EROSION OF EMBANKMENT NE QUADRANT

Path: P:\McKellar\2023\P1080163.jpg



Comments: SEVERE EROSION NORTHEAST QUADRANT

Path: P:\McKellar\2023\P1080182.jpg



Comments: WATERCOURSE UNDER BRIDGE

Path: P:\McKellar\2023\P1080170.jpg



Comments: LOOKING NORTH UPSTREAM

Path: P:\McKellar\2023\P1080171.jpg



Comments: LOOKING SOUTH DOWNSTREAM

Path: P:\McKellar\2023\P1080172.jpg

Comments:

Path:

MUNICIPAL CULVERT APPRAISAL

A. IDENTIFICATION

Culvert Name: Squaw Lake Culvert	Culvert No.: 0002
Road Name: Balsam Road	Road Section No.:
Location: 4.8 km N of Centre Road	MTO Site No.: 044-0206-
Roadside Env.: R	Posting Sign: t t t
Posting: t t t	Low Clearnc Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 587627
Bylaw Exp. Date:	Northing: 5044284
	Crossing Type: O-WAT, Over Water
	Federal Nav. Waterway: No
	Culvert Value: \$1,136,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage: 0	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks: 0	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Culvert No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Year Constructed: 1982	Cell/Span Wdth/Dia.: 6.1 m	End Treatment: A B C D
Year Extended:	Total Width/Dia: 6.1 m	Upstream: H W
Material/ Type: CPS - ACH	Max Height: 8.0 m	Downstream: H W
Crossing Skew: -00 °	Length: 13.8 m	Soil Condition: G
No of Cells/Spans: 1	Type/Depth of Fill: E 0.8 m	Foundation Type: SF - Spread footings
	Culvert Floor: EA	
----- ROAD OVER CULVERT -----		
Existing Road Class: 200	Platform Width: 8.6 m	Safety Curb/ (A) N / N 0.0 m
Operational Status: 2W - OAT	Surface Width: 6.0 m	Sidewalk and Curb (B) N / S 0.0 m
Surface Type: LCB	No. of Lanes: 2.0	Roadside Safety: (A) N FB
		(B) S FB
----- ROAD THROUGH CULVERT -----		
Existing Road Class:	No. of Lanes: 0	Traffic Barrier:
Operational Status: -	Median Type/Width: 0	Min Vertical Clearance: m
Opening Width: m	Safety Curb/ / m	
Surface Width: m	Sidewalk and Curb / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: A-2002-E	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 80	AADT: 88
<input checked="" type="checkbox"/> School <input type="checkbox"/> Bicycle	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Culvert 0002 Asset Master	10 Year Growth Factor: 1.10	20 Year AADT: 96

F. INSPECTIONS

Date: 9/28/2023	Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
-----------------	------------------------------	--------------------------------

Municipality: Township of McKellar

Culvert No.: 0002

MUNICIPAL CULVERT APPRAISAL

G. CULVERT NEEDS

Field	MCR	PCR	TON	Comments
Barrel	5	5	6-10	
Foundations	5	5	6-10	
Guiderail/Barrier	5	5	6-10	
Inlet Component	5	5	6-10	
Outlet Component	5	5	6-10	
Streams/Waterways	5	5	6-10	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Culvert				
RO-Platform Width	8.6	6.5	ADEQ	Proj Class: 200, 88 (10 YR, 80*1.1)
RO-Level of Service	A	E	ADEQ	
RO-Roadside Safety	8.8	3	ADEQ	Rdside Safety: 2

Recommended Needs

Impr.Class	Improvement Description	Time of Need	Year	Base/Const Cost	Eng/Cont	Total
------------	-------------------------	--------------	------	-----------------	----------	-------

There are no identified improvements in this inspection.

I. ENGINEERING RECOMMENDATIONS

Culvert Drawings:
 Estimated Posting: t
 Evaluated Posting: t t t
 Closure Date/Type:
 Closure Type:
 Monitoring:
 Monitoring Component:

J. DESIGN PARAMETERS

Design Class:
 Design Platform Width:
 Material/Type: -
 Width/Diameter:
 Maximum Height:
 Culvert Length:
 No. of Culverts:
 Depth of Fill:

K. IMPROVEMENT COSTS

Total Construction/Rehab	0
Total Inspection	0
<hr/>	
TOTAL	0
86613 share @100%	0

INSPECTION NOTES

Culvert No.: 0002

Culvert No. 0002, Squaw Lake Culvert, Lot 17, Concession XIV, Balsam Road, 4.80 km North of Centre Road, Township of McKellar:

- Structure is not posted with a load limit.
- 6.1 m+/- single span steel multi-plate arch culvert.
- Surface treated roadway and approach roads over culvert are in good condition.
- Steel beam guide rail has been provided in all four quadrants and across structure and are in generally good condition with minor collision damage. Terminal end treatments are provided in all four quadrants. Gabion basket retaining walls are provided in the Northeast, Northwest and Southwest quadrants and are in good condition.
- Steel multiplate arch culvert is in generally good condition with light corrosion, localized medium corrosion and encrustation at one bolt location. Improper bolt layout on West side and one bolt has been improperly installed and is loose.
- Concrete headwalls are in generally good condition with narrow stained and unstained cracks.
- Concrete wingwalls are in generally good condition with light to medium honeycombing, water staining and narrow stained and unstained cracks.
- Concrete footings are in generally good condition with light to medium erosion, localized severe erosion in the Southwest quadrant, surface rust stains, narrow to medium stained and unstained cracks, localized wide crack (1.0m², poor).
- Watercourse is obstructed with a beaver dam with no evidence of scour.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.

L. HISTORY/ GENERAL

Culvert No.: 0002

Year: 2018, cIAG Install Approach Guiderails, Est Cost: 0



AM 8:45 SEP/28/2023

Comments: LOOKING EAST AT ROADWAY OVER CULVERT
Path: P:\McKellar\2023\P1080081.jpg



AM 8:46 SEP/28/2023

Comments: LOOKING WEST AT ROADWAY OVER CULVERT
Path: P:\McKellar\2023\P1080082.jpg



Comments: SOUTH ELEVATION
Path: P:\McKellar\2023\P1080086.jpg



Comments: NORTH ELEVATION
Path: P:\McKellar\2023\P1080094.jpg



Comments: MINOR COLLISION DAMAGE GUIDE RAIL
Path: P:\McKellar\2023\P1080084.jpg



Comments: TYPICAL WEARING SURFACE
Path: P:\McKellar\2023\P1080083.jpg



Comments: VEGETATION ALONG ROADWAY

Path: P:\McKellar\2023\P1080085.jpg



Comments: LOOKING NORTH THROUGH BARREL

Path: P:\McKellar\2023\P1080089.jpg



Comments: BEAVER DAM IN WATERCOURSE

Path: P:\McKellar\2023\P1080091.jpg



Comments: MEDIUM CORROSION OF EAST BARREL WALL AT FOOTING

Path: P:\McKellar\2023\P1080092.jpg



Comments: ENCRUSTATION AT BOLT LOCATION

Path: P:\McKellar\2023\P1080093.jpg



Comments: NARROW STAINED CRACK IN WINGWALL

Path: P:\McKellar\2023\P1080087.jpg



Comments: SEVERE EROSION OF CONCRETE FOOTING
Path: P:\McKellar\2023\P1080090.jpg



Comments: LOOKING SOUTH DOWNSTREAM
Path: P:\McKellar\2023\P1080088.jpg



Comments: LOOKING NORTH UPSTREAM
Path: P:\McKellar\2023\P1080095.jpg

Comments:
Path:

MUNICIPAL CULVERT APPRAISAL

A. IDENTIFICATION

Culvert Name: Blackwater Road Culvert	Culvert No.: 0010
Road Name: Blackwater Road	Road Section No.:
Location: 2.0 km S of Hurdville Road	MTO Site No.:
Roadside Env.: R	Posting Sign: t t t
Posting: t t t	Low Clearnc Sign: Narrow Structure Sign:
Bylaw No.:	Easting: 17 592189
Bylaw Exp. Date:	Northing: 5031755
	Crossing Type: O-WAT, Over Water
	Federal Nav. Waterway: Unknown
	Culvert Value: \$1,036,000
	Old ID:

B. RAILWAY OVERPASS/UNDERPASS

Railway Level Crossing Number:	Original Board Order Number:
Railway Company:	Date:
Railway Subdivision:	Current Board Order Number:
Subdivision Mileage:	Date:
Transport Canada Crossing No.:	Seniority:
Number of Tracks:	

C. JURISDICTION

Owner: 86613	Special Designation:	Local / Area Municipality (Upper Tier Only)
Owner Share: 100.00 %	Designation 2	MunicA
<input type="checkbox"/> Shared?	Adjacent Culvert No.:	MunicB
Shared With:		Patrol:
Heritage Status: R		

D. EXISTING CONDITIONS

Year Constructed: 2017	Cell/Span Wdth/Dia.: 4.4 m	End Treatment: A B C D
Year Extended:	Total Width/Dia: 4.4 m	Upstream: H R
Material/ Type: CST - PA	Max Height: 2.9 m	Downstream: H R
Crossing Skew: 0 °	Length: 15.0 m	Soil Condition: G
No of Cells/Spans: 1	Type/Depth of Fill: E 1.0 m	Foundation Type: BD- Bedding
	Culvert Floor: SC	
----- ROAD OVER CULVERT -----		
Existing Road Class: 200	Platform Width: 8.0 m	Safety Curb/ (A) N / N 0.0 m
Operational Status: 2W - OAT	Surface Width: 6.0 m	Sidewalk and Curb (B) N / S 0.0 m
Surface Type: A	No. of Lanes: 2.0	Roadside Safety: (A) N FB
		(B) S FB
----- ROAD THROUGH CULVERT -----		
Existing Road Class:	No. of Lanes:	Traffic Barrier:
Operational Status: -	Median Type/Width:	Min Vertical Clearance: m
Opening Width: m	Safety Curb/ / m	
Surface Width: m	Sidewalk and Curb / m	

E. TRAFFIC DATA

Legal Speed Limit: 80	<u>Traffic Count</u>	<u>10 Year Traffic Forecast</u>
Route Designations	Year: 2002	Year: 2012
<input type="checkbox"/> Bus <input type="checkbox"/> Truck Route	AADT: 80	AADT:
<input type="checkbox"/> School <input type="checkbox"/> Bicycle	DHV Factor: %	DHV Factor: %
	DHV: vph	DHV: vph
	Trucks: %	Trucks: %
Source:	Peak Directional Split: %	Capacity: 0 vph
Culvert 0010 Asset Master	10 Year Growth Factor:	20 Year AADT: 0

F. INSPECTIONS

Date: 9/28/2023 Inspected By: Jeff Parkinson	Approved By: D. Baxter, P.Eng.
--	--------------------------------

Municipality: Township of McKellar

Culvert No.: 0010

MUNICIPAL CULVERT APPRAISAL

G. CULVERT NEEDS

Field	MCR	PCR	TON	Comments
Barrel	5	6	6-10	
Foundations	6	6	ADEQ	
Guiderail/Barrier	6	6	ADEQ	
Inlet Component	6	6	ADEQ	
Outlet Component	6	6	ADEQ	
Streams/Waterways	6	6	ADEQ	

H. FUNCTIONAL NEEDS

Field	Existing	Min Tolerable	Time of Need	Comments
Road Over Culvert				
RO-Platform Width	8	6.5	ADEQ	Proj Class: 200, 80 (10 YR, 80*1)
RO-Level of Service	A	E	ADEQ	
RO-Roadside Safety	3.9	3	ADEQ	Rdside Safety: 2

Recommended Needs

Impr.Class	Improvement	Description	Time of Need	Year	Base/Const Cost	Eng/Cont	Total
------------	-------------	-------------	--------------	------	-----------------	----------	-------

There are no identified improvements in this inspection.

I. ENGINEERING RECOMMENDATIONS

Culvert Drawings:
 Estimated Posting: t
 Evaluated Posting: t t t
 Closure Date/Type:
 Closure Type:
 Monitoring:
 Monitoring Component:

J. DESIGN PARAMETERS

Design Class:
 Design Platform Width:
 Material/Type: -
 Width/Diameter:
 Maximum Height:
 Culvert Length:
 No. of Culverts:
 Depth of Fill:

K. IMPROVEMENT COSTS

Total Construction/Rehab	0
Total Inspection	0
<hr/>	
TOTAL	0
86613 share @100%	0

INSPECTION NOTES

Culvert No.: 0010

Culvert No. 0010, Blackwater Road Culvert, Lot 18, Concession I, Blackwater Road, 2.0 km South of Hurdville Road, Township of McKellar:

- Structure is not posted with a load limit.
- 4.37m+/- single span steel pipe arch culvert.
- Asphalt paved roadway over the culvert is in good condition.
- Steel beam guide rail on steel posts has been provided over the structure and on the approaches and is in good condition.
- Rip rap roadway embankments are in generally good condition with minor erosion.
- Gabion basket head wall and retaining walls are in excellent condition.
- Steel pipe arch culvert is in good condition with light corrosion at the waterline.
- Watercourse is unobstructed with no evidence of scour.
- No serious evidence of structural distress.
- Structure does not require posting with a load limit.

L. HISTORY/ GENERAL

Culvert No.: 0010

Year: 2017, cRBC Replace bridge with culvert, Est Cost: 0



Comments: LOOKING WEST AT ROADWAY OVER CULVERT
Path: P:\McKellar\2023\P1080309.jpg



Comments: LOOKING EAST AT ROADWAY OVER CULVERT
Path: P:\McKellar\2023\P1080310.jpg



Comments: SOUTH ELEVATION

Path: P:\McKellar\2023\P1080312.jpg



Comments: NORTH ELEVATION

Path: P:\McKellar\2023\P1080319.jpg



Comments: MINOR EROSION OF EMBANKMENT

Path: P:\McKellar\2023\P1080311.jpg




Comments: LOOKING NORTH THROUGH BARREL

Path: P:\McKellar\2023\P1080313.jpg



Comments: LOOKING SOUTH DOWNSTREAM
Path: P:\McKellar\2023\P1080314.jpg



Comments: LOOKING SOUTH THROUGH BARREL
Path: P:\McKellar\2023\P1080316.jpg



Comments: LOOKING NORTH UPSTREAM
Path: P:\McKellar\2023\P1080317.jpg



Comments: LIGHT CORROSION OF BARREL AT WATERLINE
Path: P:\McKellar\2023\P1080315.jpg

